

# **PROBLEM SUMMARY**

Sample Rating Trend

GLYCOL


Machine Id **227108-249** 

Component
Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)

## **COMPONENT CONDITION SUMMARY**





## RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS									
Sample Status				ATTENTION	ATTENTION	ABNORMAL			
Sodium	ppm	ASTM D5185m		<u> </u>	77	<b>▲</b> 82			
Visc @ 100°C	cSt	ASTM D445	15.4	<b>12.1</b>	<b>▲</b> 11.9	<u> </u>			

Customer Id: GFL166 Sample No.: GFL0087825 Lab Number: 05920552 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

### RECOMMENDED ACTIONS

There are no recommended actions for this sample.

### HISTORICAL DIAGNOSIS

### 24 May 2023 Diag: Jonathan Hester

VISCOSITY



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.



#### 09 Mar 2023 Diag: Jonathan Hester

GLYCOL



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. Sodium and/or potassium levels remain high. Light fuel dilution occurring. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.



### 27 Sep 2022 Diag: Jonathan Hester

GLYCOL



We advise that you check for possible coolant leak. Check for low coolant level. We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. Sodium and/or potassium levels are high. There is a moderate amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.





# **OIL ANALYSIS REPORT**

DT <sup>\*</sup>



GLYCOL



Machine Id **227108-249** 

Component **Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)

### **DIAGNOSIS**

### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

### Contamination

Sodium and/or potassium levels are high. Test for glycol is negative.


#### ▲ Fluid Condition


The oil viscosity is lower than normal. The BN result indicates that there is suitable alkalinity remaining in the oil. Confirm oil type.


GAL)		Sep202	2 Mar 2023	May2023 As	ıg2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0087825	GFL0081204	GFL0074911
Sample Date		Client Info		08 Aug 2023	24 May 2023	09 Mar 2023
Machine Age	hrs	Client Info		4429	4399	4399
Oil Age	hrs	Client Info		200	600	600
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				ATTENTION	ATTENTION	ABNORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<b>▲</b> 4.0
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	26	15	12
Chromium	ppm	ASTM D5185m	>20	<1	<1	<1
Nickel	ppm	ASTM D5185m	>4	<1	<1	<1
Titanium	ppm	ASTM D5185m		1	<1	1
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>20	5	3	3
Lead	ppm	ASTM D5185m	>40	2	<1	<1
Copper	ppm	ASTM D5185m	>330	2	2	2
Tin	ppm	ASTM D5185m	>15	<1	<1	<1
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	330	335	297
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	76	75	71
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	428	426	365
Calcium	ppm	ASTM D5185m	1070	1456	1438	1366
Phosphorus	ppm	ASTM D5185m	1150	962	1003	900
Zinc	ppm	ASTM D5185m	1270	1191	1191	1056
Sulfur	ppm	ASTM D5185m	2060	3723	3852	3506
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	12	11	10
Sodium	ppm	ASTM D5185m		<u> </u>	77	<b>▲</b> 82
Potassium	ppm	ASTM D5185m	>20	10	7	6
Glycol	%	*ASTM D2982		NEG	NEG	NEG
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.9	0.3	0.2
Nitration	Abs/cm	*ASTM D7624	>20	7.5	7.2	6.9
Sulfation	Abs/.1mm	*ASTM D7415	>30	21.1	20.8	20.3
FLUID DEGRAI	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	14.2	14.9	14.4
Base Number (BN)	mg KOH/g	ASTM D2896		7.8	8.0	7.8
` '	0 0					



# **OIL ANALYSIS REPORT**










VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
<b>Emulsified Water</b>	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


I LOID I NOI	LITTILO	method	IIIIIII Dase	Current	HISTORY	HISTOTYZ
Visc @ 100°C	cSt	ASTM D445	15.4	<u> </u>	<u> </u>	<b>▲</b> 11.8

### **GRAPHS**













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package : FLEET ( Additional Tests: Glycol )

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 05920552

: GFL0087825 : 10592466

Received Diagnosed

: 10 Aug 2023 : 11 Aug 2023 Diagnostician : Jonathan Hester

GFL Environmental - 166 - Phenix City 18 Old Brickyard Rd Phenix City, AL US 36869

Contact: DEAN PEACE JR dean.peace@gflenv.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: