

OIL ANALYSIS REPORT

Sample Rating Trend


NORMAL



MACK 812099

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (9 GAL)





DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

JN 50P 15440 (GAL)	Sep2014 Apr2	015 Nov2017 Jun2020	Jan2021 Sep2022 Jan2023	Jul2023	
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0086269	GFL0086238	GFL0057645
Sample Date		Client Info		09 Aug 2023	18 Jul 2023	10 Apr 2023
Machine Age	hrs	Client Info		5164	95312	95312
Oil Age	hrs	Client Info		5164	5004	4416
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>120	4	17	15
Chromium	ppm	ASTM D5185m	>20	0	<1	<1
Nickel	ppm	ASTM D5185m	>5	0	1	3
Titanium	ppm	ASTM D5185m	>2	0	0	0
Silver	ppm	ASTM D5185m	>2	<1	0	0
Aluminum	ppm	ASTM D5185m	>20	0	1	<1
Lead	ppm	ASTM D5185m	>40	<1	<1	0
Copper	ppm	ASTM D5185m	>330	<1	2	1
Tin	ppm	ASTM D5185m	>15	0	<1	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	20	10	12
Barium	ppm	ASTM D5185m	0	2	0	1
Molybdenum	ppm	ASTM D5185m	60	66	65	64
Manganese	ppm	ASTM D5185m	0	0	<1	<1
Magnesium	ppm	ASTM D5185m	1010	751	797	838
Calcium	ppm	ASTM D5185m	1070	1169	1075	1066
Phosphorus	ppm	ASTM D5185m	1150	929	895	880
Zinc	ppm	ASTM D5185m	1270	1133	1138	1161
Sulfur	ppm	ASTM D5185m	2060	3074	2523	2634
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	2	4	4
Sodium	ppm	ASTM D5185m		0	<1	4
Potassium	ppm	ASTM D5185m	>20	2	<1	<1
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>4	0.2	0.6	0.5
Nitration	Abs/cm	*ASTM D7624	>20	5.7	8.5	7.5
Sulfation	Abs/.1mm	*ASTM D7415	>30	17.3	20.2	17.8
FLUID DEGRADATION method limit/base current history1 history2						
Oxidation	Abs/.1mm	*ASTM D7414	>25	12.0	15.5	14.5
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	7.4	5.9	5.9
(= / • /	99					



OIL ANALYSIS REPORT








VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROP	ERITES	method	ilmit/base		nistory i	nistory2
Visc @ 100°C	cSt	ASTM D445	15.4	12.5	12.6	12.8

GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10603086 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0086269 : 05923139

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Received Diagnosed

: 14 Aug 2023 : 14 Aug 2023 Diagnostician : Wes Davis

GFL Environmental - 009 - Fairburn

6905 Roosevelt Hwy Fairburn, GA US 30213

Contact: Eric Jones erjones@gflenv.com T: (678)630-9927

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: GFL009 [WUSCAR] 05923139 (Generated: 08/14/2023 16:42:43) Rev: 1