

PROBLEM SUMMARY

Sample Rating Trend



WEAR



FREIGHTLINER 14


Component


Discol Engine


Diesel Engine

PETRO CANADA DURON SHP 15W40 (13 LTR)

COMPONENT CONDITION SUMMARY







RECOMMENDATION

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE					
Lead	ppm	ASTM D5185m	>30	9 1					
Fuel	%	ASTM D3524	>5	0.8					
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	2.4					
Visc @ 100°C	cSt	ASTM D445	15.4	11.9					

Customer Id: ATRPIN Sample No.: PCA0102570 Lab Number: 05924123 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com


RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Fuel/injector System			?	We advise that you check the fuel injection system.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend





FREIGHTLINER 14

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (13 LTR)

DIAGNOSIS

Recommendation

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

Wear

The lead level is severe.

Contamination

There is a high amount of fuel present in the oil.


Fluid Condition

Fuel is present in the oil and is lowering the viscosity. The BN level is low. The oil is no longer serviceable due to the presence of contaminants.

LTR)				Aug 2023		
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0102570		
Sample Date		Client Info		10 Aug 2023		
Machine Age	mls	Client Info		552177		
Oil Age	mls	Client Info		23764		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
CONTAMINAT	TION	method	limit/base	current	history1	history2
Glycol		WC Method		NEG		
WEAR METAL	_S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>80	58		
Chromium	ppm	ASTM D5185m	>5	3		
Nickel	ppm	ASTM D5185m	>2	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>3	0		
Aluminum	ppm	ASTM D5185m	>30	1		
Lead	ppm	ASTM D5185m	>30	9 1		
Copper	ppm	ASTM D5185m	>150	2		
Tin	ppm	ASTM D5185m	>5	4		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Poron						
Boron	ppm	ASTM D5185m	0	1		
Barium	ppm	ASTM D5185m ASTM D5185m	0	1 0		
Barium	ppm	ASTM D5185m	0	0		
Barium Molybdenum	ppm	ASTM D5185m ASTM D5185m	0 60	0 56		
Barium Molybdenum Manganese	ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m	0 60 0	0 56 <1		
Barium Molybdenum Manganese Magnesium	ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	0 60 0 1010	0 56 <1 860		
Barium Molybdenum Manganese Magnesium Calcium	ppm ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	0 60 0 1010 1070	0 56 <1 860 1204		
Barium Molybdenum Manganese Magnesium Calcium Phosphorus	ppm ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	0 60 0 1010 1070 1150	0 56 <1 860 1204 927		
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc	ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	0 60 0 1010 1070 1150 1270	0 56 <1 860 1204 927 1183		
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur	ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	0 60 0 1010 1070 1150 1270 2060	0 56 <1 860 1204 927 1183 3261		
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN	ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	0 60 0 1010 1070 1150 1270 2060	0 56 <1 860 1204 927 1183 3261 current	 history1	
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon	ppm	ASTM D5185m	0 60 0 1010 1070 1150 1270 2060	0 56 <1 860 1204 927 1183 3261 current	 history1	 history2
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium	ppm ppm ppm ppm ppm ppm ppm ppm	ASTM D5185m	0 60 0 1010 1070 1150 1270 2060 limit/base	0 56 <1 860 1204 927 1183 3261 current	 history1	 history2
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium	ppm	ASTM D5185m	0 60 0 1010 1070 1150 1270 2060 limit/base >20	0 56 <1 860 1204 927 1183 3261 current 17 4	 history1	history2
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium Fuel INFRA-RED	ppm	ASTM D5185m	0 60 0 1010 1070 1150 1270 2060 limit/base >20 >5	0 56 <1 860 1204 927 1183 3261 current 17 4 2 8.0 current		history2
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium Fuel INFRA-RED Soot %	ppm	ASTM D5185m	0 60 0 1010 1070 1150 1270 2060 limit/base >20 >5 limit/base >3	0 56 <1 860 1204 927 1183 3261 current 17 4 2 8.0 current	history1 history1	history2 history2
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium Fuel INFRA-RED	ppm	ASTM D5185m	0 60 0 1010 1070 1150 1270 2060 limit/base >20 >5	0 56 <1 860 1204 927 1183 3261 current 17 4 2 8.0 current	history1 history1	history2 history2
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium Fuel INFRA-RED Soot % Nitration	ppm	ASTM D5185m ASTM D3524 method *ASTM D7844 *ASTM D7624 *ASTM D76145	0 60 0 1010 1070 1150 1270 2060 limit/base >20 >5 limit/base >3 >20	0 56 <1 860 1204 927 1183 3261 current 17 4 2 8.0 current 1.1 12.6	history1 history1	history2 history2
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium Fuel INFRA-RED Soot % Nitration Sulfation FLUID DEGRA	ppm	ASTM D5185m Method ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D7844 *ASTM D7844 *ASTM D7624 *ASTM D76124 *ASTM D76124 *ASTM D76124	0 60 0 1010 1070 1150 1270 2060 limit/base >20 >5 limit/base >3 >20 >30 limit/base	0 56 <1 860 1204 927 1183 3261 current 17 4 2 8.0 current 1.1 12.6 30.8 current	history1 history1 history1	history2 history2 history2
Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium Fuel INFRA-RED Soot % Nitration Sulfation	ppm	ASTM D5185m ASTM D3524 method *ASTM D7844 *ASTM D7624 *ASTM D76145	0 60 0 1010 1070 1150 1270 2060 limit/base >20 >5 limit/base >3 >20 >30 limit/base >25	0 56 <1 860 1204 927 1183 3261 current 17 4 2 8.0 current 1.1 12.6 30.8	history1 history1	history2 history2



OIL ANALYSIS REPORT





Certificate L2367

Report Id: ATRPIN [WUSCAR] 05924123 (Generated: 08/16/2023 10:27:40) Rev: 1

Laboratory Sample No. Lab Number Unique Number

: PCA0102570 : 05924123 : 10604070

Received Diagnosed

: 14 Aug 2023 : 16 Aug 2023 Diagnostician : Jonathan Hester

Test Package: FLEET (Additional Tests: FuelDilution, PercentFuel) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

A Truck Repair

9349 China Grove Church Road Pineville, NC US 28134

Contact: Vlad Melnichuk shop@migway.com T: (980)255-3200

Submitted By: Vlad Melnichuk