

PROBLEM SUMMARY

Area [98363821]

KR-GR-001553-NORTH - 15000 MIXER (S/N MIX C - 11513064)

Gearbox

PETRO CANADA 220 (50 QTS)

Sample Rating Trend



COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. We were unable to perform a particle count due to metal particles present in this sample.

		10 TECT	RESULTS	١.
PRURI	$-N/\Delta$	IC. IESI	RESILLS	•

NORMAL Sample Status ABNORMAL NORMAL White Metal scalar *Visual NONE **MODER** NONE VLITE

Customer Id: KRAKIR Sample No.: PCA0103227 Lab Number: 05926096 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Filter			?	We recommend you service the filters on this component if applicable.
Alert			?	We were unable to perform a particle count due to metal particles present in this sample.

HISTORICAL DIAGNOSIS

22 Apr 2023 Diag: Angela Borella

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



14 Oct 2022 Diag: Angela Borella

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



28 Jun 2022 Diag: Don Baldridge

WATER



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.





OIL ANALYSIS REPORT

Sample Rating Trend

VISUAL METAL


Area [98363821]

KR-GR-001553-NORTH - 15000 MIXER (S/N MIX C - 11513064)

Component

Gearbox

PETRO CANADA 220 (50 QTS)





DIAGNOSIS

Recommendation

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. We were unable to perform a particle count due to metal particles present in this sample.

Wear

Moderate concentration of visible metal present. All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			Oct2020 Apr2021	Oct2021 Apr2022 Oct2022	Jul2023	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0103227	PCA0093104	PCA0080327
Sample Date		Client Info		31 Jul 2023	22 Apr 2023	14 Oct 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	71	72	64
Chromium	ppm	ASTM D5185m	>15	<1	<1	<1
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	0	<1
Lead	ppm	ASTM D5185m	>100	0	0	0
Copper	ppm	ASTM D5185m	>200	<1	<1	<1
Tin	ppm	ASTM D5185m	>25	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		61	71	59
Barium	ppm	ASTM D5185m		3	0	0
Molybdenum	ppm	ASTM D5185m		383	402	405
Manganese	ppm	ASTM D5185m		3	3	2
Magnesium	ppm	ASTM D5185m		1	<1	<1
Calcium	ppm	ASTM D5185m		111	115	132
Phosphorus	ppm	ASTM D5185m		1099	1099	1121
Zinc	ppm	ASTM D5185m		157	163	161
Sulfur	ppm	ASTM D5185m		23069	23411	25676
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	14	14	13
Sodium	ppm	ASTM D5185m		10	13	12
Potassium	ppm	ASTM D5185m	>20	3	4	4
FLUID DEGRAD	OATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		2.10		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	▲ MODER	NONE	VLITE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	LIGHT
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
5 05 00\ D						ADD KDAKID



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10606043

: PCA0103227

: 05926096

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 16 Aug 2023 Diagnosed : 17 Aug 2023

Diagnostician : Jonathan Hester

Test Package : IND 2 (Additional Tests: PrtCount) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

KraftHeinz - Kirksville - Plant 8333 PCA

2504 INDUSTRIAL DR KIRKSVILLE, MO

US 63501

Contact: WALLACE WARD wallace.ward@kraftheinzcompany.com

T: (660)627-1031

F: (660)627-5887