

# **PROBLEM SUMMARY**

Sample Rating Trend


WEAR

728007 Component

**Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (12 QTS)

## **COMPONENT CONDITION SUMMARY**



## RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	NORMAL	ABNORMAL	
Aluminum	ppm	ASTM D5185m	>20	<b>△</b> 32	20	<u>^</u> 24	

Customer Id: GFL010 Sample No.: GFL0088751 Lab Number: 05927026 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

## **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

## HISTORICAL DIAGNOSIS

## 12 Jul 2023 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



## 13 Jun 2023 Diag: Angela Borella

WEAR



Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. Aluminum ppm levels are abnormal. Piston wear is indicated. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil.



### 26 May 2023 Diag: Wes Davis

NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**

Sample Rating Trend







728007

**Diesel Engine** 

## PETRO CANADA DURON SHP 15W40 (12 QTS)

## DIAGNOSIS

### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### Wear

The aluminum level is abnormal. All other component wear rates are normal.

#### Contamination

There is no indication of any contamination in the oil.


#### **Fluid Condition**

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.


QTS)		ct2020 De	2021 Apr2022 Oct2	022 Feb2023 May2023 J	un2023	
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number Sample Date		Client Info		GFL0088751 16 Aug 2023	GFL0086120 12 Jul 2023	GFL0083257 13 Jun 2023
Machine Age	hrs	Client Info		11450	11327	11138
Oil Age	hrs	Client Info		295	172	1052
Oil Changed	0	Client Info		Not Changd	Not Changd	Changed
Sample Status				ABNORMAL	NORMAL	ABNORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>90	31	15	37
Chromium	ppm	ASTM D5185m	>20	<1	<1	1
Nickel	ppm	ASTM D5185m	>2	0	0	0
Titanium	ppm	ASTM D5185m	>2	<1	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>20	<u>^</u> 32	20	<u>^</u> 24
Lead	ppm	ASTM D5185m	>40	<1	0	0
Copper	ppm	ASTM D5185m	>330	1	<1	<1
Tin	ppm	ASTM D5185m	>15	2	0	3
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	10	0	21
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	64	62	66
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	894	868	860
Calcium	ppm	ASTM D5185m	1070	1214	1132	1248
Phosphorus	ppm	ASTM D5185m	1150	994	972	1014
Zinc	ppm	ASTM D5185m	1270	1240	1211	1269
Sulfur	ppm	ASTM D5185m	2060	3367	3496	3452
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	5	3	5
Sodium	ppm	ASTM D5185m		3	6	1
Potassium	ppm	ASTM D5185m	>20	18	11	11
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>6	0.4	0.2	0.5
Nitration	Abs/cm	*ASTM D7624	>20	10.7	8.4	11.7
Sulfation	Abs/.1mm	*ASTM D7415	>30	20.9	19.0	23.9
FLUID DEGRAI	OATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	19.3	15.8	24.2
Base Number (BN)	mg KOH/g	ASTM D2896	9.8			5.3
Dase Mulliber (DIN)	iliy Noriyy	A3 1 W D2030	9.0	6.4	7.5	5.5




# **OIL ANALYSIS REPORT**




VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
<b>Emulsified Water</b>	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
ELLUD DDODE	DTIES					





FLUID PROPI	ERTIES	method	limit/base	current	history1	history
Visc @ 100°C	cSt	ASTM D445	15.4	13.1	12.8	12.9




## **GRAPHS**













Laboratory Sample No. Lab Number **Unique Number** Test Package : FLEET

: GFL0088751 : 05927026 : 10606973

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 17 Aug 2023 : 18 Aug 2023 Diagnosed Diagnostician : Don Baldridge

GFL Environmental - 010 - Stockbridge

1280 Rum Creek Parkway Stockbridge, GA US 30281

Contact: JOSHUA TINKER joshuatinker@gflenv.com T:

Certificate L2367

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: