


## **PROBLEM SUMMARY**




Component **Rear Differential** 

GEAR OIL SAE 75W90 (--- GAL)



### **COMPONENT CONDITION SUMMARY**



### RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status				ABNORMAL						
Silicon	ppm	ASTM D5185m	>75	<b>^</b> 76						

Customer Id: PERDILSC Sample No.: PCA0104880 Lab Number: 05939378 Test Package: FLEET To manage this report scan the QR code To discuss the diagnosis or test data: Sean Felton +1 919-379-4092 sfelton@wearcheckusa.com To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

## RECOMMENDED ACTIONS

There are no recommended actions for this sample.

### HISTORICAL DIAGNOSIS



## **OIL ANALYSIS REPORT**



**Rear Differential** 

GEAR OIL SAE 75W90 (--- GAL)

# Sample Rating Trend **DIRT**

### **DIAGNOSIS**

### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

All component wear rates are normal.

### Contamination

Elemental level of silicon (Si) above normal indicating ingress of seal material.

### **Fluid Condition**


The condition of the oil is acceptable for the time in service.

				Aug2023		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0104880		
Sample Date		Client Info		29 Aug 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>500	235		
Chromium	ppm	ASTM D5185m	>10	3		
Nickel	ppm	ASTM D5185m	>10	5		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	4		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>100	2		
Tin	ppm	ASTM D5185m	>10	1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	400	158		
Barium	ppm	ASTM D5185m	200	0		
Molybdenum	ppm	ASTM D5185m	12	<1		
Manganese	ppm	ASTM D5185m		13		
Magnesium	ppm	ASTM D5185m	12	5		
Calcium	ppm	ASTM D5185m	150	24		
Phosphorus	ppm	ASTM D5185m	1650	1104		
Zinc	ppm	ASTM D5185m	125	31		
Sulfur	ppm	ASTM D5185m	22500	30569		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>75	<b>▲</b> 76		
Sodium	ppm	ASTM D5185m		6		
Potassium	ppm	ASTM D5185m	>20	4		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>.2	NEG		
Free Water	scalar	*Visual		NEG		
			11			let a co
FLUID PROPE	RITES	method	limit/base	current	history1	history2

Visc @ 40°C



## **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10629990

: PCA0104880 : 05939378 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 30 Aug 2023 Diagnosed : 01 Sep 2023

Diagnostician : Sean Felton

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**PERDUE FARMS - DILLON** 

2047 HWY 9 WEST DILLON, SC US 29536

Contact: KEVIN HOOKS kevin.hooks@perdue.com

Submitted By: KEVIN HOOKS

T: (843)841-8069 F: (843)841-8070