


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id **412036**

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

GAL)		May2022	Aug ² 022 Feb ² 023	Apr2023 Jun2023	Sep.2023	
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0092516	GFL0077915	GFL0071640
Sample Date		Client Info		12 Sep 2023	12 Jun 2023	26 Apr 2023
Machine Age	hrs	Client Info		4433	3267	2660
Oil Age	hrs	Client Info		604	604	623
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	9	10	11
Chromium	ppm	ASTM D5185m	>20	<1	<1	<1
Nickel	ppm	ASTM D5185m	>4	<1	3	5
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m	>3	<1	<1	0
Aluminum	ppm	ASTM D5185m	>20	0	<1	2
Lead	ppm	ASTM D5185m	>40	0	2	0
Copper	ppm	ASTM D5185m	>330	0	2	2
Tin	ppm	ASTM D5185m	>15	0	1	0
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		0	<1	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	1	<1	0
Barium	ppm	ASTM D5185m	0	0	<1	0
Molybdenum	ppm	ASTM D5185m	60	60	63	61
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	1010	983	1034	1026
Calcium	ppm	ASTM D5185m	1070	1071	1148	1120
Phosphorus	ppm	ASTM D5185m	1150	961	1047	1030
Zinc	ppm	ASTM D5185m	1270	1257	1322	1292
Sulfur	ppm	ASTM D5185m	2060	3322	3400	3160
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	3	6	3
Sodium	ppm	ASTM D5185m		4	6	2
Potassium	ppm	ASTM D5185m	>20	2	2	3
INFRA-RED		method	limit/base	current	history1	history2
IIIIIII						
Soot %	%	*ASTM D7844	>3	0.4	0.4	0.4
	% Abs/cm	*ASTM D7844	>3 >20	0.4 8.2		0.4 8.2
Soot %					0.4 8.7 20.4	
Soot % Nitration	Abs/cm Abs/.1mm	*ASTM D7844 *ASTM D7624 *ASTM D7415	>20	8.2	8.7	8.2
Soot % Nitration Sulfation FLUID DEGRAE	Abs/cm Abs/.1mm	*ASTM D7844 *ASTM D7624 *ASTM D7415 method	>20 >30 limit/base	8.2 19.7 current	8.7 20.4 history1	8.2 17.9 history2
Soot % Nitration Sulfation	Abs/cm Abs/.1mm	*ASTM D7844 *ASTM D7624 *ASTM D7415	>20 >30 limit/base >25	8.2 19.7	8.7 20.4	8.2 17.9




OIL ANALYSIS REPORT





White Metal scala	r *Visual				
	i visuai	NONE	NONE	NONE	NONE
Yellow Metal scala	r *Visual	NONE	NONE	NONE	NONE
Precipitate scala	r *Visual	NONE	NONE	NONE	NONE
Silt scala	r *Visual	NONE	NONE	NONE	NONE
Debris scala	r *Visual	NONE	NONE	NONE	NONE
Sand/Dirt scala	r *Visual	NONE	NONE	NONE	NONE
Appearance scala	r *Visual	NORML	NORML	NORML	NORML
Odor scala	r *Visual	NORML	NORML	NORML	NORML
Emulsified Water scala	r *Visual	>0.2	NEG	NEG	NEG
Free Water scala	r *Visual		NEG	NEG	NEG


L LLOID PROPI		method			riistory i	HISTORYZ
Visc @ 100°C	cSt	ASTM D445	15.4	13.8	13.6	13.8

GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10655805

Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0092516 : 05954592

Received Diagnosed

: 18 Sep 2023 : 20 Sep 2023 Diagnostician : Wes Davis

GFL Environmental - 947 - WB Horicon HC

N7296 County Rd V Horicon, WI US 53032 Contact: Tim Kieffer

tim.kieffer@gflenv.com T: (608)219-0288

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)