

PROBLEM SUMMARY

•

Sample Rating Trend


DIRT


Machine Id **2227070**


Component **Diesel Engine**

PETRO CANADA DURON SHP 10W30 (--- QTS)

COMPONENT CONDITION SUMMARY







RECOMMENDATION

We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS

Sample Status				ABNORMAL	
Silicon	ppm	ASTM D5185m	>25	4 74	

Customer Id: PERPRIPCA Sample No.: PCA0081428 Lab Number: 05958544 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED	ACTIONS			
Action	Status	Date	Done By	Description
Check Dirt Access			?	We advise that you check the air filter, air induction system, and any areas where dirt may enter the component.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id **2227070** Component

Diesel Engine

PETRO CANADA DURON SHP 10W30 (--- 0

DIAGNOSIS

Recommendation

We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material. Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil.

				*		
rts)				Sep2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0081428		
Sample Date		Client Info		11 Sep 2023		
Machine Age	mls	Client Info		0		
Oil Age	mls	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINAT	ION	method	limit/base	-		
	ION			current	history1	history2
-uel		WC Method	>5	<1.0		
Glycol		WC Method		NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>100	34		
Chromium	ppm	ASTM D5185m	>20	<1		
Vickel	ppm	ASTM D5185m	>4	1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>3	20		
Aluminum	ppm	ASTM D5185m	>20	25		
_ead	ppm	ASTM D5185m	>40	0		
Copper	ppm	ASTM D5185m	>330	108		
Γin	ppm	ASTM D5185m	>15	3		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	257		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	50	116		
Manganese	ppm	ASTM D5185m	0	4		
Magnesium	ppm	ASTM D5185m	950	716		
Calcium	ppm	ASTM D5185m	1050	1507		
Phosphorus	ppm	ASTM D5185m	995	676		
Zinc	ppm	ASTM D5185m	1180	817		
Sulfur	ppm	ASTM D5185m	2600	2750		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	▲ 74		
Sodium	ppm	ASTM D5185m		6		
Potassium	ppm	ASTM D5185m	>20	72		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.2		
Nitration	Abs/cm	*ASTM D7624	>20	8.6		
Sulfation	Abs/.1mm	*ASTM D7415	>30	24.8		
FLUID DEGRAI	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	21.7		
Base Number (BN)	mg KOH/g	ASTM D2896		8.4		
(DIV)	9			•		



OIL ANALYSIS REPORT





Certificate L2367

Sample No. Lab Number **Unique Number**

Test Package : FLEET

: 05958544

: PCA0081428 : 10659757

Received Diagnosed Diagnostician

: 24 Sep 2023 : Don Baldridge PRINCE GEORGE, VA US 23875

Contact: MICHAEL DAVIS

MICHAELP.DAVIS@PERDUE.COM T:

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: