


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



397834

Component **Diesel Engine**

PETRO CANADA DURON SHP 10W30 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

Wear

Metal levels are typical for a new component breaking in.

Contamination

There is no indication of any contamination in the


Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

GAL)		Jan202	0 Nov2020	Aug2021 Se	p2023	
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0105333	PCA0042316	PCA0008703
Sample Date		Client Info		23 Sep 2023	05 Aug 2021	05 Nov 2020
Machine Age	mls	Client Info		62689	3692	42936
Oil Age	mls	Client Info		62689	3692	15000
Oil Changed		Client Info		Changed	Changed	Changed
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	23	51	17
Chromium	ppm	ASTM D5185m	>20	0	<1	<1
Nickel	ppm	ASTM D5185m	>4	0	<1	<1
Titanium	ppm	ASTM D5185m		0	<1	2
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>20	1	3	3
Lead	ppm	ASTM D5185m	>40	0	0	<1
Copper	ppm	ASTM D5185m	>330	<1	30	<1
Tin	ppm	ASTM D5185m	>15	0	0	4
Antimony	ppm	ASTM D5185m			0	0
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	11	18	9
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	50	57	62	52
Manganese	ppm	ASTM D5185m	0	<1	<1	<1
Magnesium	ppm	ASTM D5185m	950	971	921	952
Calcium	ppm	ASTM D5185m	1050	1297	1115	1111
Phosphorus	ppm	ASTM D5185m	995	1106	1002	976
Zinc	ppm	ASTM D5185m	1180	1344	1163	1118
Sulfur	ppm	ASTM D5185m	2600	3282	2809	2491
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	4	8	7
Sodium	ppm	ASTM D5185m		2	2	1
Potassium	ppm	ASTM D5185m	>20	2	8	7
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.1	0.5	0.2
Nitration	Abs/cm	*ASTM D7624	>20	6.1	9.6	7.9
Sulfation	Abs/.1mm	*ASTM D7415	>30	17.5	19.9	19.5
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	13.8	17.5	15.7
Base Number (BN)	mg KOH/g	ASTM D2896		8.5		



OIL ANALYSIS REPORT





Base Nu 0.0





Certificate L2367

Laboratory Sample No.

Lab Number **Unique Number**

: PCA0105333 : 05968766 : 10675317

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 04 Oct 2023 Diagnosed : 04 Oct 2023 Diagnostician

: Wes Davis

Test Package : MOB 1 (Additional Tests: TBN) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

MILLER TRUCK LEASING #118

2196 BENNETT ROAD PHILADELPHIA, PA US 19116

Contact: ROSTY VITER rviter@millertransgroup.com T: (215)552-9832

Contact/Location: ROSTY VITER - MILPHINE

F: (215)552-9892

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NEG

11.2