

PROBLEM SUMMARY


Sample Rating Trend **GLYCOL**

123015-1062

Component **Diesel Engine**

PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS											
Sample Status				ABNORMAL	NORMAL	SEVERE					
Sodium	ppm	ASTM D5185m		△ 62	3	<u>^</u> 281					
Potassium	mqq	ASTM D5185m	>20	50	4	<u>^</u> 258					

Customer Id: GFL631 Sample No.: GFL0061045 Lab Number: 05979264 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 ihester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

21 Sep 2023 Diag: Jonathan Hester

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



08 Sep 2023 Diag: Wes Davis

GLYCOL



We advise that you check for the source of the coolant leak. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. All component wear rates are normal. Test for glycol is positive. There is a high concentration of glycol present in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The oil is no longer serviceable due to the presence of contaminants.





OIL ANALYSIS REPORT

Sample Rating Trend

GLYCOL

123015-1062

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- 0

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Sodium and/or potassium levels are high. Test for glycol is negative.

▲ Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

iAL)		Sej	2023	Sep 2023 Oct20	23					
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2				
Sample Number		Client Info		GFL0061045	GFL0061047	GFL0061038				
Sample Date		Client Info		10 Oct 2023	21 Sep 2023	08 Sep 2023				
Machine Age	hrs	Client Info		15928	0	15864				
Oil Age	hrs	Client Info		64	1	590				
Oil Changed		Client Info		Not Changd	Changed	Changed				
Sample Status				ABNORMAL	NORMAL	SEVERE				
CONTAMINAT	ION	method	limit/base	current	history1	history2				
Fuel		WC Method	>5	<1.0	<1.0	<1.0				
WEAR METAL	.S	method	limit/base	current	history1	history2				
ron	ppm	ASTM D5185m	>100	3	0	15				
Chromium	ppm	ASTM D5185m	>20	<1	0	<1				
Nickel	ppm	ASTM D5185m	>4	<1	0	0				
Titanium	ppm	ASTM D5185m		<1	0	0				
Silver	ppm	ASTM D5185m	>3	0	0	0				
Aluminum	ppm	ASTM D5185m	>20	<1	<1	3				
Lead	ppm	ASTM D5185m	>40	0	0	3				
Copper	ppm	ASTM D5185m	>330	0	0	<1				
Tin	ppm	ASTM D5185m	>15	<1	0	<1				
Vanadium	ppm	ASTM D5185m		<1	0	<1				
Cadmium	ppm	ASTM D5185m		0	0	0				
ADDITIVES		method	limit/base	current	history1	history2				
Boron	ppm	ASTM D5185m	0	9	4	5				
Barium	ppm	ASTM D5185m	0	0	0	0				
Molybdenum	ppm	ASTM D5185m	60	67	38	102				
Manganese	ppm	ASTM D5185m	0	<1	0	<1				
Magnesium	ppm	ASTM D5185m	1010	879	602	975				
Calcium	ppm	ASTM D5185m	1070	1006	646	1161				
Phosphorus	ppm	ASTM D5185m	1150	980	638	991				
Zinc	ppm	ASTM D5185m	1270	1118	782	1263				
Sulfur	ppm	ASTM D5185m	2060	2907	2041	3688				
CONTAMINAN	ITS	method	limit/base	current	history1	history2				
Silicon	ppm	ASTM D5185m	>25	4	2	8				
Sodium	ppm	ASTM D5185m		<u>▲</u> 62	3	<u>^</u> 281				
Potassium	ppm	ASTM D5185m	>20	<u>^</u> 50	4	<u>^</u> 258				
		*ASTM D2982		NEG	NEG	0.10				
Glycol	%	AOTIVI DESUE								
INFRA-RED	%	method	limit/base	current	history1	history2				
INFRA-RED	%		limit/base >3	current 0.1		0.5				
INFRA-RED Soot %		method	>3	current	history1 0 4.2					
INFRA-RED Soot % Nitration	%	method *ASTM D7844	>3	current 0.1	history1	0.5				
INFRA-RED Soot % Nitration	% Abs/cm Abs/.1mm	method *ASTM D7844 *ASTM D7624 *ASTM D7415	>3 >20	current 0.1 5.0	history1 0 4.2	0.5 10.2				
INFRA-RED Soot % Nitration Sulfation FLUID DEGRA	% Abs/cm Abs/.1mm	method *ASTM D7844 *ASTM D7624 *ASTM D7415	>3 >20 >30	0.1 5.0 16.6	history1 0 4.2 17.0	0.5 10.2 19.8				
Soot % Nitration Sulfation	% Abs/cm Abs/.1mm DATION	method *ASTM D7844 *ASTM D7624 *ASTM D7415 method	>3 >20 >30 limit/base >25	0.1 5.0 16.6 current	history1 0 4.2 17.0 history1	0.5 10.2 19.8 history2				



Viscosity @ 100°C


OIL ANALYSIS REPORT




VISUAL		method	limit/base	current
White Metal	scalar	*Visual	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE
Silt	scalar	*Visual	NONE	NONE
Debris	scalar	*Visual	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML
Odor	scalar	*Visual	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG
Free Water	scalar	*Visual		NEG
TICC VValci	Scalai	VISUAI		ITLG


	18	Ahnormal													
			 	 	 		 								 ſ
	1/1														
0.0	16+	Base	 	 	 		 								
Ξ	15+	Ī													
₹3	14-		 	-		-	-	_	_	_	_	_	_	_	
	13 -	Abnormal													
	12-		 	 			 			-					







GRAPHS









history1

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NEG

history2

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NEG





Certificate L2367

Laboratory Sample No. Lab Number Unique Number

: GFL0061045 : 05979264 : 10696559

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received

: 16 Oct 2023 Diagnosed : 17 Oct 2023 Diagnostician : Jonathan Hester

Test Package : FLEET (Additional Tests: Glycol)

Contact: MITCH HERSHBERGER

T: (231)624-0848

GFL Environmental - 631 - Manistee

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F:

407 Renaissance Dr

Manistee, MI

US 49660