


# **OIL ANALYSIS REPORT**

Sample Rating Trend



NORMAL



Machine Id **639277** 

Component **Diesel Engine** 

PETRO CANADA DURON SHP 10W30 (--- QTS)

## DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

#### Wear

Metal levels are typical for a new component breaking in.

## Contamination

There is no indication of any contamination in the


## **Fluid Condition**

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

QTS)			Nov2022	Jun2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0097323	PCA0071687	
Sample Date		Client Info		27 Jun 2023	30 Nov 2022	
Machine Age	mls	Client Info		58090	28826	
Oil Age	mls	Client Info		29264	28826	
Oil Changed		Client Info		Changed	Changed	
Sample Status				NORMAL	ATTENTION	
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	
Glycol		WC Method		NEG	NEG	
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	30	35	
Chromium	ppm	ASTM D5185m	>20	<1	1	
Nickel	ppm	ASTM D5185m	>4	<1	1	
Titanium	ppm	ASTM D5185m		16	15	
Silver	ppm	ASTM D5185m	>3	0	1	
Aluminum	ppm	ASTM D5185m	>20	8	27	
Lead	ppm	ASTM D5185m	>40	<1	2	
Copper	ppm	ASTM D5185m	>330	4	11	
Tin	ppm	ASTM D5185m	>15	1	2	
Vanadium	ppm	ASTM D5185m		0	<1	
Cadmium	ppm	ASTM D5185m		<1	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	8	16	
Barium	ppm	ASTM D5185m	0	<1	0	
Molybdenum	ppm	ASTM D5185m	50	52	49	
Manganese	ppm	ASTM D5185m	0	1	2	
Magnesium	ppm	ASTM D5185m	950	825	885	
Calcium	ppm	ASTM D5185m	1050	1237	1504	
Phosphorus	ppm	ASTM D5185m	995	992	1039	
Zinc	ppm	ASTM D5185m	1180	1260	1363	
Sulfur	ppm	ASTM D5185m	2600	2981	3738	
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	14	12	
Sodium	ppm	ASTM D5185m		3	3	
Potassium	ppm	ASTM D5185m	>20	23	89	
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.4	0.3	
Nitration	Abs/cm	*ASTM D7624	>20	10.6	10.9	
Sulfation	Abs/.1mm	*ASTM D7415	>30	22.3	23.7	
FLUID DEGRA	OATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	18.2	19.6	
Base Number (BN)	mg KOH/g	ASTM D2896		6.1	6.6	



## **OIL ANALYSIS REPORT**







Laboratory Sample No. Lab Number **Unique Number** 

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: PCA0097323 : 05984531 : 10701826

Received : 20 Oct 2023 Diagnosed

: 23 Oct 2023 Test Package : MOB 1 ( Additional Tests: TBN )

Diagnostician : Wes Davis

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**MILLER TRUCK LEASING #123** 

**66 KELLER AVENUE** LANCASTER, PA US 17601

Contact: RON ROBERTS rroberts@millertransgroup.com

Contact/Location: RON ROBERTS - MILLAN

T: (717)945-6205 F: (717)945-5818