


OIL ANALYSIS REPORT



Machine Id **738672**

Component **Diesel Engine**

PETRO CANADA DURON SHP 10W30 (--- 0

DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The BN level is low. The condition of the oil is acceptable for the time in service.

TS)				Oct2023		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0093387		
Sample Date		Client Info		23 Oct 2023		
Machine Age	mls	Client Info		222752		
Oil Age	mls	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Glycol		WC Method		NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	76		
Chromium	ppm	ASTM D5185m	>20	4		
Nickel	ppm	ASTM D5185m	>4	1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>3	<1		
Aluminum	ppm	ASTM D5185m	>20	16		
Lead	ppm	ASTM D5185m	>40	<1		
Copper	ppm	ASTM D5185m	>330	30		
Tin	ppm	ASTM D5185m	>15	1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	11		
Barium	ppm	ASTM D5185m	0	5		
Molybdenum	ppm	ASTM D5185m	50	80		
Manganese	ppm	ASTM D5185m	0	1		
Magnesium	ppm	ASTM D5185m	950	937		
Calcium	ppm	ASTM D5185m	1050	1286		
Phosphorus	ppm	ASTM D5185m	995	1065		
Zinc	ppm	ASTM D5185m	1180	1257		
Sulfur	ppm	ASTM D5185m	2600	2136		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	8		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	37		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	1.7		
Nitration	Abs/cm	*ASTM D7624	>20	16.9		
Miliation						
Nitration Sulfation	Abs/.1mm	*ASTM D7415	>30	30.1		
			>30 limit/base	30.1 current	history1	history2
Sulfation						



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number

Unique Number

: 06000286 : 10728646

: PCA0093387

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 09 Nov 2023 Diagnostician : Jonathan Hester

: 07 Nov 2023

Test Package : MOB 1 (Additional Tests: TBN)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

MILLER TRUCK LEASING #117

2666 LEISCZS BRIDGE RD LEESPORT, PA US 19533

Contact: JAMEY RITZ

jritz@millertransgroup.com T:

F: