


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



721018-361460

Component

Diesel Engine

PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

Metal levels are typical for a new component breaking in.

Contamination

There is no indication of any contamination in the


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

GAL)		Sep 2022	Mar2023 May2023	Jul2023 Oct2023 N	ov2023	
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0088145	GFL0088100	GFL0088077
Sample Date		Client Info		01 Dec 2023	14 Nov 2023	24 Oct 2023
Machine Age	hrs	Client Info		829	735	590
Oil Age	hrs	Client Info		0	0	467
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ΓΙΟΝ	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	_S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	13	19	15
Chromium	ppm	ASTM D5185m	>20	<1	2	2
Nickel	ppm	ASTM D5185m	>4	<1	0	<1
Titanium	ppm	ASTM D5185m		<1	<1	<1
Silver	ppm	ASTM D5185m	>3	0	0	0
Aluminum	ppm	ASTM D5185m	>20	2	2	2
Lead	ppm	ASTM D5185m	>40	0	2	2
Copper	ppm	ASTM D5185m	>330	1	2	<1
Tin	ppm	ASTM D5185m	>15	0	2	2
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	3	20	36
Barium	ppm	ASTM D5185m	0	0	0	4
Molybdenum	ppm	ASTM D5185m	60	65	55	51
Manganese	ppm	ASTM D5185m	0	0	2	2
Magnesium	ppm	ASTM D5185m	1010	984	849	835
Calcium	ppm	ASTM D5185m	1070	1156	1136	1176
Phosphorus	ppm	ASTM D5185m	1150	1116	855	795
Zinc	ppm	ASTM D5185m	1270	1317	1024	979
Sulfur	ppm	ASTM D5185m	2060	3403	2568	2544
CONTAMINAN	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	3	12	14
Sodium	ppm	ASTM D5185m		4	31	18
Potassium	ppm	ASTM D5185m	>20	2	7	4
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.8	0.5	0.4
Nitration	Abs/cm	*ASTM D7624	>20	10.4	8.6	8.3
Sulfation	Abs/.1mm	*ASTM D7415	>30	21.0	20.1	20.7
FLUID DEGRA	NOITAD.	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	18.6	17.1	17.2
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	7.3	8.3	8.7



OIL ANALYSIS REPORT





Visco	sity @ 1	.00°C				
18 - Abnorm	al					_
17 Base						
(2-16 Base 15 Base						_
13 Abnorm	al					
ep15/22	lar10/23 -	May18/23 -	Jul11/23 -	0ct6/23 -	Nov14/23 -	


VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROP	ERITES	metnoa	ilmit/base	current	nistory i	nistory2
Visc @ 100°C	cSt	ASTM D445	15.4	14.1	14.1	14.1

GRAPHS













Certificate L2367

Laboratory Sample No. Lab Number Test Package : FLEET

: GFL0088145 : 06027314 Unique Number : 10777105

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 07 Dec 2023

Diagnosed : 08 Dec 2023 Diagnostician : Wes Davis

GFL Environmental - 820 - Joplin Hauling

3700 West 7th Street Joplin, MO US 64801

Contact: James Jarrett jjarrett@gflenv.com

T: (417)310-2802

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)