

# **PROBLEM SUMMARY**

## Sample Rating Trend

**WEAR** 





Machine Id **211006-632124** 


Component **Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)

## **COMPONENT CONDITION SUMMARY**







#### RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATION	C TEST	RESULT	S			
Sample Status				ABNORMAL	NORMAL	NORMAL
Copper	ppm	ASTM D5185m	>330	<b>410</b>	<1	3

Customer Id: GFL820 Sample No.: GFL0088142 Lab Number: 06027316 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Sean Felton +1 919-379-4092 sfelton@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

### **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

#### HISTORICAL DIAGNOSIS

#### 23 Oct 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



### 06 Oct 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor.All component wear rates are normal. Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



#### 28 Aug 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor.All component wear rates are normal. Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**

Sample Rating Trend

New/2022 April0223 Many/2023 Juli2023 April0223 Oct/2023 Oct/2023 New/2023

WEAR



**211006-632124** 

Component

**Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (--- GAL)

### DIAGNOSIS

#### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### Wear

The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other component wear rates are normal.

#### Contamination

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.


#### **Fluid Condition**

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

AAL)		Nov2022 A	Apr2023 May2023 Jul202	23 Aug 2023 Oct 2023 Oct 2023	Nov2023	
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0088142	GFL0088074	GFL0088112
Sample Date		Client Info		30 Nov 2023	23 Oct 2023	06 Oct 2023
Machine Age	hrs	Client Info		3860	3716	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	Changed
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	55	4	30
Chromium	ppm	ASTM D5185m	>20	5	0	<1
Nickel	ppm	ASTM D5185m	>4	1	0	0
Titanium	ppm	ASTM D5185m		<1	<1	0
Silver	ppm	ASTM D5185m	>3	<1	0	0
Aluminum	ppm	ASTM D5185m	>20	91	10	77
Lead	ppm	ASTM D5185m	>40	<1	0	0
Copper	ppm	ASTM D5185m	>330	<u>410</u>	<1	3
Tin	ppm	ASTM D5185m	>15	2	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	45	0	0
Barium	ppm	ASTM D5185m	0	0	0	0
Molybdenum	ppm	ASTM D5185m	60	53	51	59
Manganese	ppm	ASTM D5185m	0	4	0	0
Magnesium	ppm	ASTM D5185m	1010	551	842	939
Calcium	ppm	ASTM D5185m	1070	1709	932	1010
Phosphorus	ppm	ASTM D5185m	1150	778	916	949
Zinc	ppm	ASTM D5185m	1270	938	1111	1207
Sulfur	ppm	ASTM D5185m	2060	2609	2649	2721
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	8	3	7
Sodium	ppm	ASTM D5185m		7	1	2
Potassium	ppm	ASTM D5185m	>20	236	23	180
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.3	0.1	0.6
Nitration	Abs/cm	*ASTM D7624	>20	6.6	4.9	9.5
Sulfation	Abs/.1mm	*ASTM D7415	>30	18.1	17.1	19.7
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	14.1	12.7	16.8
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	8.3	8.2	7.0



# **OIL ANALYSIS REPORT**



To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

jjarrett@gflenv.com

T: (417)310-2802

F: