

# **PROBLEM SUMMARY**

Sample Rating Trend


GLYCOL

Machine Id 10867 Component

**Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (40 GAL)

### **COMPONENT CONDITION SUMMARY**



### RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	NORMAL	NORMAL	
Potassium	ppm	ASTM D5185m	>20	<b>44</b>	9	5	

Customer Id: GFL084 Sample No.: GFL0098983 Lab Number: 06028426 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

### **RECOMMENDED ACTIONS**

There are no recommended actions for this sample.

#### HISTORICAL DIAGNOSIS

06 Nov 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



20 Oct 2023 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



25 Sep 2023 Diag: Wes Davis

NORMAL




Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





# **OIL ANALYSIS REPORT**

Sample Rating Trend



**GLYCOL** 



Machine Id 10867 Component

**Diesel Engine** 

PETRO CANADA DURON SHP 15W40 (40 GAL)

## DIAGNOSIS

#### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

#### Wear

All component wear rates are normal.

#### Contamination

Sodium and/or potassium levels are high. Test for glycol is negative.


#### **Fluid Condition**


The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.


GAL)						
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0098983	GFL0099035	GFL0099046
Sample Date		Client Info		29 Nov 2023	06 Nov 2023	20 Oct 2023
Machine Age	mls	Client Info		211373	208730	206624
Oil Age	mls	Client Info		204515	204515	204515
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>75	26	19	15
Chromium	ppm	ASTM D5185m	>5	<1	<1	<1
Nickel	ppm	ASTM D5185m	>4	0	0	<1
Titanium	ppm	ASTM D5185m	>2	<1	<1	<1
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>15	4	3	3
Lead	ppm	ASTM D5185m	>25	0	0	0
Copper	ppm	ASTM D5185m	>100	1	<1	<1
Tin	ppm	ASTM D5185m	>4	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0	0	<1
Barium	ppm	ASTM D5185m	0	5	<1	3
Molybdenum	ppm	ASTM D5185m	60	71	59	61
Manganese	ppm	ASTM D5185m	0	0	0	0
Magnesium	ppm	ASTM D5185m	1010	1014	903	912
Calcium	ppm	ASTM D5185m	1070	1194	1035	1099
Phosphorus	ppm	ASTM D5185m	1150	1129	947	990
Zinc	ppm	ASTM D5185m	1270	1318	1192	1239
Sulfur	ppm	ASTM D5185m	2060	3313	3090	3603
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	9	6	7
Sodium	ppm	ASTM D5185m		45	11	5
Potassium	ppm	ASTM D5185m	>20	<b>44</b>	9	5
Glycol	%	*ASTM D2982		NEG	NEG	NEG
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>6	0.6	0.6	0.4
Nitration	Abs/cm	*ASTM D7624	>20	8.0	7.9	6.8
Sulfation	Abs/.1mm	*ASTM D7415	>30	19.4	19.5	18.8
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	15.1	15.0	14.3
Base Number (BN)	mg KOH/g	ASTM D2896	9.8	7.2	8.4	8.5
(214)						



## **OIL ANALYSIS REPORT**










VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
<b>Emulsified Water</b>	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROPE	ERTIES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	14.0	14.0	14.1

#### **GRAPHS**













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: GFL0098983 : 06028426 : 10778217

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 07 Dec 2023

: 11 Dec 2023 Diagnosed : Jonathan Hester Diagnostician

Test Package : FLEET ( Additional Tests: Glycol )

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 084 - Clarksville

699 Jack Miller Boulevard Clarksville, TN

US 37042 Contact: ROBERT THIBAULT

robert.thibault@gflenv.com

T: (931)552-7276 F: (931)572-9674