


# **OIL ANALYSIS REPORT**



**NORMAL** 



# CUMMINS 10854

Component

**Front Diesel Engine** 

{not provided} (--- GAL)

### DIAGNOSIS

### Recommendation

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.

All component wear rates are normal.

### Contamination

Fuel content negligible. No other contaminants were detected in the oil.


### **Fluid Condition**

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

			,	Jan 2024		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0109061		
Sample Date		Client Info		05 Jan 2024		
Machine Age	hrs	Client Info		3953		
Oil Age	hrs	Client Info		3953		
Oil Changed		Client Info		N/A		
Sample Status				NORMAL		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
Glycol		WC Method		NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>75	16		
Chromium	ppm	ASTM D5185m	>5	1		
Nickel	ppm	ASTM D5185m	>4	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m		2		
Lead	ppm	ASTM D5185m	>25	<1		
Copper	ppm	ASTM D5185m		1		
Tin	ppm	ASTM D5185m	>4	1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		11		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		53		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		604		
Calcium	ppm	ASTM D5185m		1000		
Phosphorus	ppm	ASTM D5185m		696		
Zinc	ppm	ASTM D5185m		942		
Sulfur	ppm	ASTM D5185m		2422		
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	10		
Sodium			0	10		
	ppm	ASTM D5185m		1		
Potassium	ppm ppm	ASTM D5185m ASTM D5185m	>20			
Potassium Fuel				1		
	ppm	ASTM D5185m	>20	1 3		
Fuel	ppm	ASTM D5185m ASTM D3524	>20 >3.0	1 3 1.7		
Fuel INFRA-RED	ppm %	ASTM D5185m ASTM D3524 method	>20 >3.0 limit/base	1 3 1.7 current	 history1	  history2
Fuel INFRA-RED Soot %	ppm %	ASTM D5185m ASTM D3524 method *ASTM D7844	>20 >3.0 limit/base >6	1 3 1.7 current	history1	history2
Fuel INFRA-RED Soot % Nitration	ppm % % Abs/cm Abs/.1mm	ASTM D5185m ASTM D3524 method *ASTM D7844 *ASTM D7624 *ASTM D7415	>20 >3.0 limit/base >6 >20	1 3 1.7 current 0.6 9.8	history1	history2
Fuel INFRA-RED Soot % Nitration Sulfation FLUID DEGRAI	ppm % % Abs/cm Abs/.1mm	ASTM D5185m ASTM D3524 method *ASTM D7844 *ASTM D7624 *ASTM D7415 method	>20 >3.0 limit/base >6 >20 >30 limit/base	1 3 1.7 current 0.6 9.8 19.4 current	history1	history2
Fuel INFRA-RED Soot % Nitration Sulfation	ppm % % Abs/cm Abs/.1mm	ASTM D5185m ASTM D3524 method *ASTM D7844 *ASTM D7624 *ASTM D7415	>20 >3.0 limit/base >6 >20 >30	1 3 1.7 current 0.6 9.8 19.4	history1	history2 history2



## **OIL ANALYSIS REPORT**







Laboratory Sample No. Lab Number Unique Number

: GFL0109061 : 06055270 : 10821219

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Recieved : 09 Jan 2024 Diagnosed

: 11 Jan 2024 Diagnostician : Sean Felton **Test Package**: FLEET (Additional Tests: FuelDilution, PercentFuel)

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

GFL Environmental - 009 - Fairburn

6905 Roosevelt Hwy Fairburn, GA US 30213 Contact: Eric Jones erjones@gflenv.com

T: (678)630-9927