

OIL ANALYSIS REPORT

Sample Rating Trend

NORMAL



Machine Id **238274**

Component **Diesel Engine**

PETRO CANADA DURON SHP 10W30 (--- QTS)

DIAGNOSIS

Recommendation

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. No other contaminants were detected in the oil.

Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

le Number	Client Info	ı	PCA0097345				
MPLE INFORMATION	method	limit/base	current	history1			
		Dec2023					

SAMI LL INI OTT	VII/TTTOTT	method	IIIIII/Dase	Current	Thistory	HISTOTYZ
Sample Number		Client Info		PCA0097345		
Sample Date		Client Info		13 Dec 2023		
Machine Age	mls	Client Info		14285		
Oil Age	mls	Client Info		14285		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINATI	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Water		WC Method	>0.2	NEG		
Glycol		WC Method		NEG		
WEAR METALS	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	81		
Chromium	ppm	ASTM D5185m	>20	1		
Nickel	ppm	ASTM D5185m	>4	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>3	<1		
Aluminum	ppm	ASTM D5185m	>20	25		
Lead	ppm	ASTM D5185m	>40	0		
Copper	ppm	ASTM D5185m	>330	32		
Tin	ppm	ASTM D5185m	>15	3		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
	1-1-			J		
ADDITIVES	1-1-	method	limit/base	current	history1	history2
ADDITIVES Boron	ppm		limit/base		history1	history2
		method		current	,	
Boron	ppm	method ASTM D5185m	2	current 42		
Boron Barium	ppm ppm	method ASTM D5185m ASTM D5185m	2	current 42 26		
Boron Barium Molybdenum	ppm ppm ppm	method ASTM D5185m ASTM D5185m ASTM D5185m	2 0 50	current 42 26 46		
Boron Barium Molybdenum Manganese	ppm ppm ppm	method ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	2 0 50 0	current 42 26 46 9		
Boron Barium Molybdenum Manganese Magnesium	ppm ppm ppm ppm	method ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	2 0 50 0 950	current 42 26 46 9 523		
Boron Barium Molybdenum Manganese Magnesium Calcium	ppm ppm ppm ppm ppm	method ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	2 0 50 0 950 1050	current 42 26 46 9 523 1579		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus	ppm ppm ppm ppm ppm ppm	method ASTM D5185m	2 0 50 0 950 1050 995	current 42 26 46 9 523 1579 802		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc	ppm ppm ppm ppm ppm ppm ppm ppm	method ASTM D5185m	2 0 50 0 950 1050 995 1180	current 42 26 46 9 523 1579 802 945		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur	ppm ppm ppm ppm ppm ppm ppm ppm	method ASTM D5185m	2 0 50 0 950 1050 995 1180 2600	current 42 26 46 9 523 1579 802 945 2474		
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN	ppm ppm ppm ppm ppm ppm ppm ppm ppm	method ASTM D5185m	2 0 50 0 950 1050 995 1180 2600	current 42 26 46 9 523 1579 802 945 2474 current	 history1	
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	method ASTM D5185m	2 0 50 0 950 1050 995 1180 2600	current 42 26 46 9 523 1579 802 945 2474 current 10	 history1	
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	method ASTM D5185m	2 0 50 0 950 1050 995 1180 2600 limit/base	current 42 26 46 9 523 1579 802 945 2474 current 10 0	history1	history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	method ASTM D5185m	2 0 50 0 950 1050 995 1180 2600 limit/base >25 >20	current 42 26 46 9 523 1579 802 945 2474 current 10 0 61	history1	history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium INFRA-RED	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	method ASTM D5185m method ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	2 0 50 0 950 1050 995 1180 2600 limit/base >25 >20	current 42 26 46 9 523 1579 802 945 2474 current 10 0 61 current	history1 history1	history2 history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium INFRA-RED Soot %	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	method ASTM D5185m method ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m ASTM D5185m	2 0 50 0 950 1050 995 1180 2600 limit/base >25 >20	current 42 26 46 9 523 1579 802 945 2474 current 10 0 61 current 0.3	history1 history1	history2 history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium INFRA-RED Soot % Nitration	ppm	method ASTM D5185m method ASTM D5185m ASTM D5185m *ASTM D5185m ASTM D78185m ASTM D78185m ASTM D7844 *ASTM D7844	2 0 50 0 950 1050 995 1180 2600 limit/base >25 >20	current 42 26 46 9 523 1579 802 945 2474 current 10 0 61 current 0.3 8.1	history1 history1	history2 history2
Boron Barium Molybdenum Manganese Magnesium Calcium Phosphorus Zinc Sulfur CONTAMINAN Silicon Sodium Potassium INFRA-RED Soot % Nitration Sulfation	ppm	method ASTM D5185m method ASTM D5185m ASTM D5185m *ASTM D5185m ASTM D78185m ASTM D78185m ASTM D7844 *ASTM D7844	2 0 50 0 950 1050 995 1180 2600 limit/base >25 >20 limit/base >3 >20 >30	current 42 26 46 9 523 1579 802 945 2474 current 10 0 61 current 0.3 8.1 22.8	history1 history1	history2 history2

Contact/Location: RON ROBERTS - MILLAN



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number

: PCA0097345 : 06084554

Unique Number : 10871999

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 09 Feb 2024 : 12 Feb 2024

Tested Diagnosed : 12 Feb 2024 - Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Test Package : MOB 1 (Additional Tests: TBN)

T: (717)945-6205 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (717)945-5818

66 KELLER AVENUE

Contact: RON ROBERTS rroberts@millertransgroup.com

LANCASTER, PA

US 17601