


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id **649913**

Component **Diesel Engine**

PETRO CANADA DURON SHP 10W30 (--- QTS)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. No other contaminants were detected in the oil.

Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

QTS)			0ct2023	Feb2024		
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0116999	PCA0106275	
Sample Date		Client Info		05 Feb 2024	13 Oct 2023	
Machine Age	mls	Client Info		27224	16569	
Oil Age	mls	Client Info		0	0	
Oil Changed		Client Info		N/A	Not Changd	
Sample Status				NORMAL	NORMAL	
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	
Water		WC Method	>0.2	NEG	NEG	
Glycol		WC Method		NEG	NEG	
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	53	33	
Chromium	ppm	ASTM D5185m	>20	4	2	
Nickel	ppm	ASTM D5185m	>4	<1	0	
Titanium	ppm	ASTM D5185m		<1	0	
Silver	ppm	ASTM D5185m	>3	0	<1	
Aluminum	ppm	ASTM D5185m	>20	52	43	
Lead	ppm	ASTM D5185m	>40	3	0	
Copper	ppm	ASTM D5185m	>330	306	300	
Tin	ppm	ASTM D5185m	>15	4	3	
Vanadium	ppm	ASTM D5185m		<1	0	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	30	33	
Barium	ppm	ASTM D5185m	0	<1	0	
Molybdenum	ppm	ASTM D5185m	50	46	42	
Manganese	ppm	ASTM D5185m	0	4	4	
Magnesium	ppm	ASTM D5185m	950	574	552	
Calcium	ppm	ASTM D5185m	1050	1792	1587	
Phosphorus	ppm	ASTM D5185m	995	792	783	
Zinc	ppm	ASTM D5185m	1180	953	917	
Sulfur	ppm	ASTM D5185m	2600	1969	2033	
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	7	7	
Sodium	ppm	ASTM D5185m		10	9	
Potassium	ppm	ASTM D5185m	>20	142	116	
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.6	0.4	
Nitration	Abs/cm	*ASTM D7624	>20	10.5	9.0	
Sulfation	Abs/.1mm	*ASTM D7415	>30	22.6	22.2	
FLUID DEGRA	DATION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	24.7	22.1	
Base Number (BN)	mg KOH/g	ASTM D2896		7.4	8.5	



OIL ANALYSIS REPORT







Laboratory Sample No. Lab Number

Unique Number: 10874434

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0116999 : 06086989

Received **Tested** Diagnosed

: 14 Feb 2024 - Don Baldridge Test Package : MOB 1 (Additional Tests: TBN)

: 13 Feb 2024

: 13 Feb 2024

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

MILLER TRUCK LEASING #119

39 INDUSTRIAL AVE HASBROUCK HEIGHTS, NJ US 07604

Contact: MIKE LONGETTE

mlongette@millertransgroup.com

T: F: (201)528-7053

Report Id: MILRUT [WUSCAR] 06086989 (Generated: 02/14/2024 11:57:05) Rev: 1

Contact/Location: MIKE LONGETTE - MILRUT