

OIL ANALYSIS REPORT

Sample Rating Trend





Diesel Engine

PETRO CANADA DURON HP 15W40 (--- LTR)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

Wear

Metal levels are typical for a new component breaking in.

Contamination


Fuel content negligible. There is no indication of any contamination in the oil.


Fluid Condition


The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.




OIL ANALYSIS REPORT











Unique Number : 10884018 Test Package : MOB 2 (Additional Tests: FuelDilution, PercentFuel) Contact: RON INGRAM Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. ron.ingram@ingrampaving.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (256)825-6878 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Laboratory

Sample No.

Lab Number

F: