

PROBLEM SUMMARY

Sample Rating Trend

DIRT




VOLVO 26553

Component **Transmission**

{not provided} (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.

PROBLEMAT	IC TEST	Γ RESULT	S		
Sample Status				SEVERE	
Silicon	ppm	ASTM D5185m	>50	132	
Dehris	scalar	*Vigual	NONE	MODER	

Customer Id: PERCANNC Sample No.: PCA0118957 Lab Number: 06106830 Test Package: FLEET

To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com


To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED	ACTIONS			
Action	Status	Date	Done By	Description
Resample			?	We recommend an early resample to monitor this condition.

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT





VOLVO 26553

Component

Transmission

{not provided} (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal indicating ingress of seal material.


Fluid Condition


The condition of the fluid is acceptable for the time in service.

				Feb2024		
SAMPLE INFOR	RMATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0118957		
Sample Date		Client Info		19 Feb 2024		
Machine Age	mls	Client Info		0		
Oil Age	mls	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				SEVERE		
CONTAMINA [*]	TION	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR META	LS	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	37		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m		<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>50	3		
Lead	ppm	ASTM D5185m	>50	<1		
Copper	ppm	ASTM D5185m	>200	34		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m	>10	0		
Cadmium	ppm	ASTM D5185m		0		
	ррпп			-		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		17		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		2		
Manganese	ppm	ASTM D5185m		17		
Magnesium	ppm	ASTM D5185m		3		
Calcium	ppm	ASTM D5185m		700		
Phosphorus	ppm	ASTM D5185m		714		
Zinc	ppm	ASTM D5185m		12		
Sulfur	ppm	ASTM D5185m		4131		
CONTAMINA	NTS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	132		
Sodium	ppm	ASTM D5185m		3		
Potassium	ppm	ASTM D5185m	>20	10		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Precipitate	scalar	*Visual	NONE	NONE		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	▲ MODER		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.1	NEG		
Free Water	scalar	*Visual		NEG		
04 00) D			_			DED 0 44 11 16




OIL ANALYSIS REPORT





Ferrous Alloys

Non-ferrous Metals







Laboratory Sample No.

0.05 Lo oo

Feb19/24

Lab Number : 06106830 Unique Number: 10910327

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0118957

Received **Tested** Diagnosed

:01 Mar 2024 : 06 Mar 2024

: 06 Mar 2024 - Jonathan Hester

PERDUE FARMS INC - GARAGE

189 PERDUE WAY CANDOR, NC US 27229

Contact: Service Manager

Test Package: FLEET (Additional Tests: Glycol) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: