

PROBLEM SUMMARY

Sample Rating Trend

DIRT


Machine Id

GENCOR VIRGIN COLLECTOR

Gearbox

PETRO CANADA 220 (5 GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATI	PROBLEMATIC TEST RESULTS						
Sample Status				SEVERE			
Silicon	ppm	ASTM D5185m	>50	288			

Customer Id: KARWAU Sample No.: PCA0087846 Lab Number: 06142401 Test Package: IND 2 To manage this report scan the QR code To discuss the diagnosis or test data: Don Baldridge +1 don.b505@comcast.net To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com


RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description	
Check Dirt Access				We advise that you check all areas where dirt can enter the system.	

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

GENCOR VIRGIN COLLECTOR

Gearbox

acai bo

PETRO CANADA 220 (5 GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0087846		
Sample Date		Client Info		04 Mar 2024		
Machine Age	yrs	Client Info		4		
Oil Age	yrs	Client Info		2		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
CONTAMINAT	ION	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	75		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m	>10	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	0		
Lead	ppm	ASTM D5185m	>50	0		
Copper	ppm	ASTM D5185m	>200	0		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		40		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		2		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		4		
Phosphorus	ppm	ASTM D5185m		246		
Zinc	ppm	ASTM D5185m		18		
Sulfur	ppm	ASTM D5185m		6919		
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	288		
Sodium	ppm	ASTM D5185m		1		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID DEGRA	NOITAC	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.39		



OIL ANALYSIS REPORT





Certificate 12367

Laboratory Sample No.

Lab Number : 06142401 Unique Number : 10967209

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0087846

Test Package : IND 2

Received : 08 Apr 2024 Tested : 09 Apr 2024

Diagnosed

: 11 Apr 2024 - Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.

US 53963 Contact: DAVE KARTECHNER dave@kartechnerbrothers.com T: (920)324-2874

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) **KARTECHNERS**

WAUPUN, WI

N11829 COUNTY RD I