

PROBLEM SUMMARY

Sample Rating Trend






Machine Id
812102
Component
Diesel Engine
Fluid

PETRO CANADA DURON SHP 15W40 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check for the source of water entry. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE	NORMAL	NORMAL		
Water	%	ASTM D6304	>0.2	▲ 6.75				
ppm Water	ppm	ASTM D6304	>2000	67500				
Emulsified Water	scalar	*Visual	>0.2	0.2%	NEG	NEG		

Customer Id: GFL010 Sample No.: GFL0118105 Lab Number: 06178421 Test Package: FLEET



To manage this report scan the QR code

To discuss the diagnosis or test data: Jonathan Hester +1 919-379-4092 x4092 jhester@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	We recommend that you drain the oil and perform a filter service on this component if not already done.		
Change Filter			?	We recommend that you drain the oil and perform a filter service on this component if not already done.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Water Access			?	We advise that you check for the source of water entry.		

HISTORICAL DIAGNOSIS

23 Apr 2024 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



IORMAI



09 Apr 2024 Diag: Wes Davis
Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



NORMAL



12 Mar 2024 Diag: Wes Davis


Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend





Machine Id
812102
Component
Diesel Engine
Fluid

PETRO CANADA DURON SHP 15W40 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

▲ Contamination

There is a high concentration of water present in the oil.


Fluid Condition

The oil is no longer serviceable due to the presence of contaminants.


N SHP 15W4U (
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GFL0118105	GFL0118062	GFL0115702
Sample Date		Client Info		13 May 2024	23 Apr 2024	09 Apr 2024
Machine Age	hrs	Client Info		5297	5178	5059
Oil Age	hrs	Client Info		452	333	214
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				SEVERE	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>3.0	<1.0	<1.0	<1.0
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>120	7	6	4
Chromium	ppm	ASTM D5185m	>20	<1	0	0
Nickel	ppm	ASTM D5185m	>5	<1	0	0
Titanium	ppm	ASTM D5185m	>2	0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>20	2	0	<1
_ead	ppm	ASTM D5185m	>40	<1	0	0
Copper	ppm	ASTM D5185m	>330	0	0	0
Γin	ppm	ASTM D5185m	>15	4	0	<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	24	4	11
Barium	ppm	ASTM D5185m	0	<1	0	0
Molybdenum	ppm	ASTM D5185m	60	57	67	61
Manganese	ppm	ASTM D5185m	0	<1	0	<1
Magnesium	ppm	ASTM D5185m	1010	797	961	858
Calcium	ppm	ASTM D5185m	1070	1004	1214	1042
Phosphorus	ppm	ASTM D5185m	1150	922	1027	935
Zinc	ppm	ASTM D5185m	1270	1156	1308	1113
Sulfur	ppm	ASTM D5185m	2060	3060	3456	3073
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	3	2	3
Sodium	ppm	ASTM D5185m				2
	ppiii	ASTIVI DOTOSIII		<1	2	_
	ppm	ASTM D5185m	>20	<1 <1	0	0
Potassium			>20 >0.2			
Potassium Water	ppm	ASTM D5185m		<1	0	0
Potassium Water opm Water	ppm %	ASTM D5185m ASTM D6304	>0.2	<1 △ 6.75	0	0
Potassium Water opm Water	ppm % ppm	ASTM D5185m ASTM D6304 ASTM D6304	>0.2	<1 6.75 67500	0 	0
Potassium Water opm Water Glycol INFRA-RED	ppm % ppm	ASTM D5185m ASTM D6304 ASTM D6304 *ASTM D2982	>0.2 >2000	<1 ▲ 6.75 ▲ 67500 NEG	0 NEG	0 NEG
Potassium Water opm Water Glycol INFRA-RED Goot %	ppm % ppm %	ASTM D5185m ASTM D6304 ASTM D6304 *ASTM D2982 method	>0.2 >2000 limit/base	<1 6.75 67500 NEG current 0.7	0 NEG history1	0 NEG history2
Potassium Water ppm Water Glycol	ppm % ppm %	ASTM D5185m ASTM D6304 ASTM D6304 *ASTM D2982 method *ASTM D7844	>0.2 >2000 limit/base >4	<1 ▲ 6.75 ▲ 67500 NEG current	0 NEG history1	0 NEG history2
Potassium Water opm Water Glycol INFRA-RED Soot % Nitration	ppm % ppm % % Abs/cm Abs/.1mm	ASTM D5185m ASTM D6304 ASTM D6304 *ASTM D2982 method *ASTM D7844 *ASTM D7624 *ASTM D7415	>0.2 >2000 limit/base >4 >20	<1	0 NEG history1 0.4 7.4	0 NEG history2 0.3 6.5
Potassium Water opm Water Glycol INFRA-RED Soot % Nitration Sulfation	ppm % ppm % % Abs/cm Abs/.1mm	ASTM D5185m ASTM D6304 ASTM D6304 *ASTM D2982 method *ASTM D7844 *ASTM D7624 *ASTM D7415	>0.2 >2000 limit/base >4 >20 >30	<1	0 NEG history1 0.4 7.4 19.0	0 NEG history2 0.3 6.5 18.3





OIL ANALYSIS REPORT




**********	oxidation				
Abnormal	ulfation				
^		_			· Person
-	San	-	A. C.	- and and	
Automa .		~	~~		~
		~	\sim		~
Nov16/22 Feb21/23		~	$\stackrel{\sim}{\sim}$	Jan12/24	~













FLUID PROPE	ERTIES	method	limit/base	current	history1	history2
Visc @ 100°C	cSt	ASTM D445	15.4	14.0	12.8	13.1

GRAPHS













Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : GFL0118105 Lab Number : 06178421 Unique Number : 11029747

Received **Tested**

: 14 May 2024 : 17 May 2024 Diagnosed : 17 May 2024 - Jonathan Hester

1280 Rum Creek Parkway Stockbridge, GA US 30281 Contact: JOSHUA TINKER

GFL Environmental - 010 - Stockbridge

joshuatinker@gflenv.com T:

Certificate 12367

Test Package : FLEET (Additional Tests: Glycol, KF) To discuss this sample report, contact Customer Service at 1-800-237-1369.

 st - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: GFL010 [WUSCAR] 06178421 (Generated: 05/17/2024 11:10:12) Rev: 1

Submitted By: JOSHUA TINKER

F: