

OIL ANALYSIS REPORT

DT







Machine Id
1P2308
Component

Component

Diesel Engine

PETRO CANADA DURON SHP 10W30 (--- QTS)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

Wear

Metal levels are typical for a new component breaking in.

Contamination

There is no indication of any contamination in the oil

Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

QTS)			Jan2024	May2024		
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0126988	PCA0117059	
Sample Date		Client Info		29 May 2024	31 Jan 2024	
Machine Age	mls	Client Info		10600	4954	
Oil Age	mls	Client Info		0	0	
Oil Changed		Client Info		Changed	N/A	
Sample Status				NORMAL	ABNORMAL	
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	
Water		WC Method	>0.2	NEG	NEG	
Glycol		WC Method		NEG	NEG	
WEAR METAL	.S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	48	48	
Chromium	ppm	ASTM D5185m	>20	<1	<1	
Nickel	ppm	ASTM D5185m	>4	0	0	
Titanium	ppm	ASTM D5185m		<1	<1	
Silver	ppm	ASTM D5185m	>3	0	0	
Aluminum	ppm	ASTM D5185m	>20	5	9	
Lead	ppm	ASTM D5185m	>40	2	1	
Copper	ppm	ASTM D5185m	>330	33	108	
Tin	ppm	ASTM D5185m	>15	2	3	
Vanadium	ppm	ASTM D5185m		0	<1	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	24	194	
Barium	ppm	ASTM D5185m	0	0	2	
Molybdenum	ppm	ASTM D5185m	50	59	13	
Manganese	ppm	ASTM D5185m	0	2	2	
Magnesium	ppm	ASTM D5185m	950	826	113	
Calcium	ppm	ASTM D5185m	1050	1099	1010	
Phosphorus	ppm	ASTM D5185m	995	1052	842	
Zinc	ppm	ASTM D5185m	1180	1221	979	
Sulfur	ppm	ASTM D5185m	2600	3399	2776	
CONTAMINAN	ITS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	16	<u>^</u> 50	
Sodium	ppm	ASTM D5185m		4	<1	
Potassium	ppm	ASTM D5185m	>20	<1	5	
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.4	0.2	
Nitration	Abs/cm	*ASTM D7624	>20	8.1	7.1	
Sulfation	Abs/.1mm	*ASTM D7415	>30	19.4	20.8	
FLUID DEGRAI	NOITAC	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	15.9	17.5	
Base Number (BN)	mg KOH/g	ASTM D2896		7.9	4.5	



OIL ANALYSIS REPORT





Certificate 12367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PCA0126988 Lab Number : 06209808 Unique Number : 11082672

Received **Tested** Diagnosed

: 15 Jun 2024 : 15 Jun 2024 - Wes Davis Test Package : MOB 1 (Additional Tests: TBN)

: 14 Jun 2024

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Contact: MIKE LONGETTE mlongette@millertransgroup.com T: Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (201)528-7053

Report Id: MILRUT [WUSCAR] 06209808 (Generated: 06/15/2024 15:31:39) Rev: 1

Contact/Location: MIKE LONGETTE - MILRUT

MILLER TRUCK LEASING #119

HASBROUCK HEIGHTS, NJ

39 INDUSTRIAL AVE

US 07604