


OIL ANALYSIS REPORT

__



NORMAL



Machine Id **631680**

Diesel Engine

PETRO CANADA DURON SHP 10W30 (--- GAL

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

Wear

Metal levels are typical for a new component breaking in.

Contamination

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.


Fluid Condition

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

GAL)		Jul	12023	Feb 2024 Jun 20.	24	
SAMPLE INFORI	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PCA0125182	PCA0114602	PCA0102927
Sample Date		Client Info		08 Jun 2024	08 Feb 2024	27 Jul 2023
Machine Age	mls	Client Info		55427	34124	15726
Oil Age	mls	Client Info		55427	34124	15726
Oil Changed		Client Info		Not Changd	Changed	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINAT	ION	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METAL	S	method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	41	79	69
Chromium	ppm	ASTM D5185m	>20	2	2	2
Nickel	ppm	ASTM D5185m	>4	<1	0	1
Titanium	ppm	ASTM D5185m		18	0	0
Silver	ppm	ASTM D5185m	>3	<1	0	0
Aluminum	ppm	ASTM D5185m	>20	32	72	65
Lead	ppm	ASTM D5185m	>40	0	0	<1
Copper	ppm	ASTM D5185m	>330	93	339	296
Tin	ppm	ASTM D5185m	>15	3	6	9
Vanadium	ppm	ASTM D5185m		<1	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	2	18	21	35
Barium	ppm	ASTM D5185m	0	0	0	2
Molybdenum	ppm	ASTM D5185m	50	47	40	43
Manganese	ppm	ASTM D5185m	0	1	3	4
Magnesium	ppm	ASTM D5185m	950	816	555	513
Calcium	ppm	ASTM D5185m	1050	1433	1419	1700
Phosphorus	ppm	ASTM D5185m	995	1064	679	723
Zinc	ppm	ASTM D5185m	1180	1311	845	898
Sulfur	ppm	ASTM D5185m	2600	3128	1566	2203
CONTAMINAN	TS	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	5	6	7
Sodium	ppm	ASTM D5185m		6	3	3
Potassium	ppm	ASTM D5185m	>20	77	195	189
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	0.9	1.1	0.6
Nitration	Abs/cm	*ASTM D7624	>20	9.3	11.4	9.7
Sulfation	Abs/.1mm	*ASTM D7415	>30	21.5	24.0	23.4
FLUID DEGRA	NOITAC	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	17.8	25.3	23.7
Base Number (BN)	mg KOH/g	ASTM D2896		7.6	7.0	8.3



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

: PCA0125182 Lab Number : 06222047 Unique Number : 11100244

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 27 Jun 2024 **Tested** : 27 Jun 2024

Diagnosed : 27 Jun 2024 - Wes Davis Test Package : MOB 1 (Additional Tests: TBN)

To discuss this sample report, contact Customer Service at 1-800-237-1369.

 st - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

MILLER TRUCK LEASING #118

2196 BENNETT ROAD PHILADELPHIA, PA US 19116

Contact: ROSTY VITER rviter@millertransgroup.com

T: (215)552-9832 F: (215)552-9892

Contact/Location: ROSTY VITER - MILPHINE