

Sample No: VCP353431
Oil Type: NOT GIVEN
Job No: 8-376175

SAMPLE	INFORMATION			
Sample Number		VCP353431	 	
Sample Date		24 Aug 2023	 	
Machine Hours		1040	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONI	DITION			
Visc @ 40°C	cSt	92.4	 	
VOLVO	UNIATION			
	IINATION		 	
Silicon	ppm	■ 9	 	
Sodium	ppm	■ 3	 	
Potassium	ppm	2	 	
WEAR M	ETALS			
Iron	ppm	177	 	
Copper	ppm	■3	 	
Lead	ppm	■<1	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	2	 	
Chromium	ppm	□ 7	 	
Molybdenum	ppm	17	 	
Nickel	ppm	■<1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	4	 	
/anadium	ppm	0	 	
VOLVO			 	
ADDITIV	ES			
Calcium	ppm	3972	 	
Magnesium	ppm	10	 	
Zinc	ppm	710	 	
Phosphorus	ppm	630	 	
Barium	ppm	21	 	
Boron	ppm	15	 	

STRONGCO EQUIPMENT INC.

1640 ENTERPRISE ROAD MISSISSAUGA, ON CA L4W 4L4 Contact: Janice Cripps jcripps@strongco.com T: (905)565-3876 F: (905)670-2338

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SHEMISUnique No:5631584Signed:Wes DavisReport Date:25 Aug 2023



CONSTRUCTION EQUIPMENT





GRAPHS

