

CONSTRUCTION EQUIPMENT 568198 VOLVO A30G 752866 - TRANSMISSION (AUTO)



Sample No: VCP422145

Oil Type: **VOLVO AUTOMATIC TRANSMISSION FLUID AT102**

Job No: 568198

CAMPI	E INFORMATION			
			VCD202206	
Sample Number		VCP422145	VCP393206	
Sample Date		05 Jul 2023	13 Feb 2023	
Machine Hours		1096	526	
Oil Hours		1096	526	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	NORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	29.2	29.4	
	CSt		□ 25.4	
VOLVO				
CONTAI	MINATION			
Silicon	ppm	1 5	1 5	
Sodium	ppm	3	3	
Potassium	ppm	2	<u> </u>	
	1-1-	_	_	
VOLVO	AFTALC			
WEAR	JE I WE?	<u> </u>		
Iron	ppm	■ 25	1 9	
Copper	ppm	18	1 3	
Lead	ppm	■0	0	
Tin	ppm	4	3	
Aluminum	ppm	18	1 0	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm	■<1	0	
Nickel	ppm	2	1	
Titanium	ppm	0	0	
Silver	ppm	■0	0	
Manganese	ppm	4	□ 3	
Vanadium	ppm	0	0	
ADDITIV	/FC			
		- 60	E-70	
Calcium	ppm	69	1 70	
Magnesium	ppm	0	0	
Zinc	ppm	0	4	
Phosphorus	ppm	■198	183	
Barium	ppm	0	0	
Boron	ppm	7 6	88	



RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: **RIPTAM Unique No:** 10551229 Signed: Wes Davis Report Date: 12 Jul 2023



CONSTRUCTION EQUIPMENT





GRAPHS

