

## CONSTRUCTION EQUIPMENT X58223 VOLVO ECR235EL 315285 - SWING DRIVE



Sample No: VCP384643
Oil Type: NOT GIVEN
Job No: X58223

VOLVO	INFORMATIO	N		
	INFURMATIU	<del></del> -		
Sample Number		VCP384643	 	
Sample Date		05 Jul 2023	 	
Machine Hours		992	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>173</b>	 	
		_		
VOLVO	AINA TION			
LUNIAN	MINATION			
Silicon	ppm	<b>14</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>0</b>	 	
WEAR N	METALS			
Iron	ppm	<b>158</b>	 	
Copper	ppm	■13	 	
Lead	ppm	■0	 	
Tin	ppm	0	 	
Aluminum	ppm	<b>1</b>	 	
Chromium	ppm	■4	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	3	 	
Vanadium	ppm	0	 	
variadium	PPIII	· ·		
VOLVO			 	
<b>ADDITIV</b>	/ES			
Calcium	ppm	0	 	
Magnesium	ppm	0	 	
Zinc	ppm	9	 	
Phosphorus	ppm	349	 	
Barium	ppm	0	 	
Boron	ppm	0	 	
	-	-		



SCOTT EQUIPMENT COMPANY LLC - Saint Rose
PO BOX 997
SAINT ROSE, LA
US 70087
Contact: DENISE CORVERS

dcorvers@scottcompanies.com T: (504)461-0961

T: (504)461-0961 F: (504)461-0970

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SCOSAIUnique No:10552312Signed:Don BaldridgeReport Date:13 Jul 2023



## **CONSTRUCTION EQUIPMENT**





