

CONSTRUCTION EQUIPMENT SPM580157 VOLVO EC380E 315082 - SWING DRIVE



Sample No: VCP420644

Oil Type: GEAR OIL SAE 80W90

Job No: SPM580157

CVMDIE	INFORMATION				
	INFURMATION				
Sample Number		VCP420644	VCP403575	VCP364029	
Sample Date		13 Jul 2023	16 Mar 2023	26 Aug 2022	
Machine Hours		3213	2412	540	
Oil Hours		0	0	0	
Oil Changed		Not Changd	Not Changd	Changed	
Sample Status		NORMAL	NORMAL	NORMAL	
OIL CON	DITION				
Visc @ 40°C	cSt	172	<u> </u>	174	
	CSL	172	<u> </u>	174	
VOLVO					
CONTAM	IINATION				
Silicon	ppm	10	1 3	■8	
Sodium	ppm	■<1	2	- <1	
Potassium	ppm	□ 0	■0	0	
WEAR M	IETALS				
Iron	ppm	□46	■ 88	143	
Copper	ppm	4	7	■ 18	
Lead	ppm	0	0	0	
Tin	ppm	0	0	0	
Aluminum	ppm	1	1	2	
Chromium	ppm	■1	2	2	
Molybdenum	ppm	■8	<1	1 0	
Nickel	ppm	0	0	0	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	■<1	1 2	3	
Vanadium	ppm	0	0	0	
	PPIII		0	- U	
VOLVO	IFC				
ADDITIV	FZ				
Calcium	ppm	■2585	2521	1 7	
Magnesium	ppm	123	1 5	□ 0	
Zinc	ppm	1192	1 031	1 7	
Phosphorus	ppm	■923	■889	■ 343	
Barium	ppm	0	0	4	
Boron	ppm	1	0	□ 0	



UNITED SCRAP 1545 S CICERO AVE CICERO, IL US 60804 Contact: RON LUCHTENBURG rluchten@unitedscrap.com T:

Diagnosis

F:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:UNICICILUnique No:10574665Signed:Sean FeltonReport Date:28 Jul 2023



CONSTRUCTION EQUIPMENT





