Sample No: VCP412588

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

**Job No:** SWA287923 RYAN INC

SAMPLE	INFORMATION			
Sample Number	_	VCP412588	 	
Sample Date		25 Jul 2023	 	
Machine Hours		4708	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONI	NITION			
		= 20.4		
Visc @ 40°C	cSt	<b>28.4</b>	 	
VOLVO				
CONTAM	IINATION			
Silicon	ppm	<b>5</b>	 	
Sodium	ppm	<b>3</b>	 	
Potassium	ppm	<b>2</b>	 	
Otassiam	РРП			
VOLVO				
WEAR M	IETALS			
Iron	ppm	<b>■</b> 26	 	
Copper	ppm	<b>15</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>2</b>	 	
Aluminum	ppm	<b>11</b>	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>2</b>	 	
Nickel	ppm	<b>2</b>	 	
Titanium	ppm	0	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<b>1</b>	 	
Vanadium	ppm	<1	 	
ADDITIV	ES			
Calcium	ppm	<b>9</b> 1	 	
Magnesium	ppm	<b>5</b>	 	
Zinc	ppm	<b>12</b>	 	
Phosphorus	ppm	■209	 	
Barium	ppm	<b>■</b> 0	 	
Boron	ppm	<b>108</b>	 	

## **ALTA EQUIPMENT COMPANY**

5210 REESE ROAD DAVIE, FL US 33314 Contact: N. FACEY nfacey@altaequipfl.com T: (954)581-4744 F: (954)583-0318

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0095Unique No:10578276Signed:Wes DavisReport Date:01 Aug 2023



## **CONSTRUCTION EQUIPMENT**





