

CONSTRUCTION EQUIPMENT VOLVO EC480EL 310945 - SWING DRIVE



Sample No: VCP421642
Oil Type: NOT GIVEN

Job No:

VOLVO	E INFORMATION			
	INFURMATION			
Sample Number		VCP421642	VCP421656	
Sample Date		08 Aug 2023	08 Aug 2023	
Machine Hours		6796	6796	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	NORMAL	
OIL CON	DITION			
Visc @ 40°C	cSt	44.1	45.3	
CUNTAN	MINATION			
_			= 13	
Silicon	ppm	9	12	
Sodium	ppm	0	- <1	
Potassium	ppm	■2	1	
VOLVO				
WEAR N	METALS			
Iron	ppm	<u> </u>	<u> </u>	
Copper		19	25	
Lead	ppm	= <1	1 <1	
Tin	ppm	0	<1	
Aluminum	ppm	1		
	ppm		1	
Chromium	ppm	□ <1	10	
Molybdenum	ppm	8	10	
Nickel	ppm	■0	- <1	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	<1	<1	
Vanadium	ppm	0	0	
VOLVO				
ADDITIV	VES			
Calcium	ppm	446	558	
Magnesium	ррт	71	95	 -
Zinc		487	636	
Phosphorus	ppm	419	548	
Barium	ppm	0	0	
	ppm	-	23	
Boron	ppm	16	23	



UNITED RENTALS 5357 NC-11 N WINTERVILLE, NC US 28590 Contact: SKYLAR HERRING sherring1@ur.com T: (252)414-2088

Diagnosis

F:

Resample at the next service interval to monitor. NOTE: one of two samples received with same ID and sampling date.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:UNIWINVCUnique No:10617020Signed:Don BaldridgeReport Date:24 Aug 2023



CONSTRUCTION EQUIPMENT





