

CONSTRUCTION EQUIPMENT VOLVO NOT GIVEN 3 10908 - SWING DRIVE



Sample No: VCP402638

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

SAMPLE	E INFORMATION	N		
Sample Number		VCP402638	 	
Sample Date		16 Sep 2023	 	
Machine Hours		6557	 	
Oil Hours		6557	 	
Oil Changed		Changed	 	
Sample Status		SEVERE	 	
VOLVO	DITION			
OIL CON			 <u>.</u>	
Visc @ 40°C	cSt	198	 	
VOLVO				
CONTAN	MINATION			
Silicon		47	 	
Sodium	ppm	■ 4/	 	
Potassium	ppm		 	
Potassium	ppm	4	 	
VOLVO				
WEAR N	NETALS			
Iron	ppm	6639	 	
Copper	ppm	41	 	
Lead	ppm	-<1	 	
Tin	ppm	-<1	 	
Aluminum	ppm	11	 	
Chromium	ppm	62	 	
Molybdenum	ppm	■8	 	
Nickel	ppm	2	 	
Titanium	ppm	2	 	
Silver	ppm	0	 	
Manganese	ppm	61	 	
Vanadium	ppm	<1	 	
ADDITIV	VES			
Calcium	ppm	63	 	
Magnesium	ppm	7	 	
Zinc	ppm	■99	 	
Phosphorus	ppm	786	 	
Barium	ppm	■0	 	
Boron	ppm	4	 	
Boron			 	

ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com T:

F: (239)481-3302

Diagnosis

The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:VOLVO0090Unique No:10657955Signed:Jonathan HesterReport Date:22 Sep 2023



CONSTRUCTION EQUIPMENT





