

## CONSTRUCTION EQUIPMENT VOLVO ECR355EL 314257 - SWING DRIVE



Sample No:VCP0007371Oil Type:NOT GIVEN

Job No:

Boron

	INFORMATIO	N		
Sample Number	_	VCP0007371	 	
Sample Date		25 Sep 2023	 	
Machine Hours		493	 	
Oil Hours		493	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	182	 	
	AINATION			
Silicon	ppm	13	 	
Sodium	ppm	□ <1	 	
Potassium	ppm		 	
	P			
VOLVO				
WEAR N	METALS			
Iron	ppm	437	 	
Copper	ppm	<b>4</b> 3	 	
Lead	ppm	■ <1	 	
Tin	ppm	0	 	
Aluminum	ppm	2	 	
Chromium	ppm	6	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	<b>□</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	9	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	/ES			
Calcium	ppm	3	 	
Magnesium	ppm	<1	 	
Zinc	ppm	40	 	
Phosphorus	ppm	254	 	
Barium	ppm	2	 	



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256 Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com T: F: (904)737-1260

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	VOLVO0092		
Unique No:	10670397		
Signed:	Don Baldridge		
Report Date:	01 Oct 2023		

0

ppm


Submitted By: TECHNICIAN ACCOUNT

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: VOLVO0092 [WUSCAR] 05963846 (Generated: 10/01/2023 12:31:19) Rev: 1

Submitted By: TECHNICIAN ACCOUNT