

CONSTRUCTION EQUIPMENT

X17862 APAC VOLVO EC480EL 314911 - DIESEL ENGINE



Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: X17862 APAC





SCOTT EQUIPMENT COMPANY LLC - Jackson

3860 I-55 South JACKSON, MS US 39212

Contact: DWIGHT MCDOUGAL DMCDOUGAL@SCOTTCOMPANIES.COM

T:

F: (601)326-3359

Diagnosis

We advise that you check the fuel injection system. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Light fuel dilution occurring. Fuel is present in the oil and is lowering the viscosity. The BN result indicates that there is suitable alkalinity remaining in the oil.

Depot:VOLVO8771Unique No:10696496Signed:Don BaldridgeReport Date:17 Oct 2023

ppm

ppm

ppm

ppm

ppm

ppm

1575

461

992

829

0

20

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus



CONSTRUCTION EQUIPMENT





