

CONSTRUCTION EQUIPMENT SWO-068407 VOLVO EC380EL 310021 - COOLANT



Sample No: VCP428705

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No: SWO-068407

SAMPLE INFORMATION					
Sample Number	-	VCP428705	VCP428932	VCP407527	VCP356255
Sample Date		21 Dec 2023	07 Sep 2023	18 May 2023	03 Nov 2022
Machine Hours		10648	10247	9662	9133
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
COOLANT CONDITION					
рН	Scale 0-14	■8.67	■8.06	■ 8.35	7.74
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	■ NT	■ NT	■976	■ NT
Percentage Glycol	%	45.1	50.7	50.7	55.4
Freezing Point	°C	□ -24	□-35	- 35	-47
CONTAMINATION					
Coolant Appearance		normal	normal	normal	normal
Coolant Color		Yllow	Yllow	Yllow	Yllow



WHITAKER CONTRACTING 692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976 Contact: BROTHER WHITAKER BrotherWhitaker@whitaker-contracting.com T: (256)298-3905 F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:WHIGUNUnique No:10809942Signed:Jonathan HesterReport Date:04 Jan 2024



CONSTRUCTION EQUIPMENT





GRAPHS

