

 Sample No:
 VCP430908

 Oil Type:
 COWIN 80W90

 Job No:
 SW0068852

SAMPLE	INFORMATIO	N		
Sample Number		VCP430908	 	
Sample Date		11 Jan 2024	 	
Machine Hours		1097	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>155</b>	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>■19</b>	 	
Sodium	ppm	■0	 	
Potassium	ppm	<b>2</b>	 	
	Pletti			
WEAR N	METALS			
Iron	ppm	■297	 	
Copper	ppm	<b>-&lt;1</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■7</b>	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	5	 	
Vanadium	ppm	0	 	
ADDITIV	IES			
Calcium	ppm	8	 	
Magnesium	ppm	0	 	
Zinc	ppm	0	 	
Phosphorus	ppm	362	 	
		_		



## **COWIN EQUIPMENT COMPANY**

7950 PITTMAN AVE
PENSACOLA, FL
US 32534
Contact: HUGH DOBBS
HDOBBS@COWIN.COM
T: (850)479-3004
F: (850)474-1602

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8247Unique No:10834519Signed:Wes DavisReport Date:18 Jan 2024

6

ppm

ppm

Barium

Boron



## **CONSTRUCTION EQUIPMENT**





