

Sample No: VCP445573

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No: 702725 ATLAS ORG

VOLVO	E INFORMATION	1		
Sample Number		VCP445573	VCP414766	
Sample Date		24 Apr 2024	19 Sep 2023	
Machine Hours		2978	2014	
Oil Hours		2978	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	ABNORMAL	
OIL CON	IDITION			
		= 27.4	27 4	
Visc @ 40°C	cSt	27.1	27.4	
VOLVO				
CONTAI	MINATION			
Water	%	NEG	NEG	
Silicon	ppm	112 0	9	
Sodium	ppm	5	5	
Potassium	ppm	4	2	
Totassiam	PPIII			
VOLVO				
WEAR I	METALS			
Iron	ppm	123	<u> </u>	
Copper	ppm	■8	7	
Lead	ppm	-<1	0	
Tin	ppm	■ 0	- <1	
Aluminum	ppm	2	2	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm		0	
Nickel	ppm	-< 1	0	
Titanium	ppm	<1	0	
Silver	ppm	■<1	0	
Manganese	ppm	10	10	
Vanadium	ppm	<1	0	
	1-1-			
VOLVO	UFC			
ADDITIV	NE7			
Calcium	ppm	■82	78	
Magnesium	ppm	2	4	
Zinc	ppm	■36	27	
Phosphorus	ppm	195	177	
Barium	ppm	2	4	
Boron	ppm	65	69	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0093Unique No:11036713Signed:Don BaldridgeReport Date:22 May 2024



CONSTRUCTION EQUIPMENT





