



PAUL MATTEAUS NO UNIT VPA045967 - GENSET

Sample No: VPA045967

Oil Type: PETRO CANADA 15W40

SAMPLE INFORM	ATION			
Sample Number		VPA045967	 	
Sample Date		30 Mar 2023	 	
Machine Hours		117	 	
Oil Hours		117	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
	C:	—42.0		
Visc @ 100°C	cSt	13.9	 	
Oxidation (PA)	%	68	 	
CONTAMINATION				
Soot %	%	0	 	
Nitration (PA)	%	61	 	
Sulfation (PA)	%	61	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	■ 9	 	
Sodium	ppm	■3	 	
Potassium	ppm	■ 0	 	
WEAR METALS				
Iron	ppm	■ 3	 	
Copper	ppm	2	 	
Lead	ppm	0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	44	 	
Nickel	ppm	■0	 	
Titanium	ppm	<1	 	
Silver	ppm	□ 0	 	
Manganese	ppm		 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	1247	 	
Magnesium	ppm	■ 664	 	
Zinc	ppm	■819	 	
Phosphorus	ppm	770	 	
Barium	ppm	2	 	
Boron	ppm	43	 	

NORTH WESTERN MARINE SERVICES LTD

3645 MOUNTAIN HWY NORTH VANCOUVER, BC CA V7K 2H7 Contact: ROB CULLEN rj@northwesternmarine.com T: (604)328-0530

Diagnosis

F:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP533931Unique No:5555235Signed:Kevin MarsonReport Date:10 Apr 2023

OIL ANALYSIS REPORT



