



REED KOCH 502043 CATERPILLAR 5T9172 - INBOARD - PORT GEARBOX

Sample No: VPA056878
Oil Type: NOT GIVEN

SAMPLE INFORM	ATION			
Sample Number		VPA056878	 	
Sample Date		17 Jul 2023	 	
Machine Hours		5511	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ATTENTION	 	
OIL CONDITION				
Visc @ 40°C	cSt	■89.3	 	
CONTAMINATION				
Silicon	ppm	11	 	
Sodium	ppm	2	 	
Potassium	ppm	■0	 	
WEAR METALS				
PQ		■37	 	
Iron	ppm	■27	 	
Copper	ppm	4	 	
Lead	ppm	<u> </u>	 	
Tin	ppm	■<1	 	
Aluminum	ppm	0	 	
Chromium	ppm	■ 0	 	
Molybdenum	ppm	49	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	<1	 	
ADDITIVES				
Calcium	ppm	3717	 	
Magnesium	ppm	20	 	
Zinc	ppm	1179	 	
Phosphorus	ppm	1049	 	
Barium	ppm	0	 	
Boron	ppm	496	 	

Endor Marine LLC - Coastal Marine - 152124 4300 11th Ave. NW SEATTLE, WA US 98107 Contact: WILLOW YANARELLA service@coastalmarineengine.com T: (206)784-3703 F: (206)784-8823

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.Clutch wear is indicated. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VP794951Unique No:10564853Signed:Jonathan HesterReport Date:24 Jul 2023

OIL ANALYSIS REPORT



