



## JAKE FARLEY NORTHERN LIGHTS 8642-36501C - STARBOARD GENSET

Sample No: VPA051735

**Oil Type:** CAT DIESEL ENGINE OIL 15W40

SAMPLE INFORMAT	TION			
Sample Number		VPA051735	 	
Sample Date		14 Aug 2023	 	
Machine Hours		0	 	
Oil Hours		100	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDITION				
Visc @ 100°C	cSt	<b>13.3</b>	 	
Base Number (BN)		■ 13.3 ■ 8.9	 	
, ,	mg KOH/g	_		
Oxidation (PA)	%	46	 	
CONTAMINATION				
Soot %	%	<b>■0.1</b>	 	
Nitration (PA)	%	51	 	
Sulfation (PA)	%	49	 	
` ,	%	NEG		
Glycol				
Fuel	%	<1.0	 	
Silicon	ppm	■8	 	
Sodium	ppm	■9	 	
Potassium	ppm	<b>1</b>	 	
WEAR METALS				
Iron	ppm	<b>5</b>	 	
Copper	ppm	<b>■</b> <1	 	
Lead	ppm	■0	 	
Tin	ppm	<b>0</b>	 	
Aluminum		■0	 	
Chromium	ppm	<b>■</b> <1	 	
	ppm	_		
Molybdenum	ppm	<b>45</b>	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<b>■ &lt;1</b>	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	<b>1695</b>	 	
Magnesium	ppm	■558	 	
Zinc	ppm	■949	 	
Phosphorus	ppm	■813	 	
Barium	ppm	<b>2</b>	 	
Boron	ppm	<b>138</b>	 	
20.011	77111			

## **Edward's Marine and Sons**

12741 Sunset Ave OCEAN CITY, MD US 21842

Contact: Edward Bartholme

edwards marine @comcast.net; can a stasio @wearcheck us a.com

F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot: VP551029
Unique No: 10618328
Signed: Sean Felton
Report Date: 25 Aug 2023

## OIL ANALYSIS REPORT



