## **OIL ANALYSIS REPORT**

### MOVEABLE FEAST 20072432 - INBOARD GEARBOX

Sample No: VPA059508

**Oil Type:** SHELL ROTELLA T 30

#### SAMPLE INFORMATION Sample Number VPA059508 The Talaria Company 01 Nov 2023 Sample Date Machine Hours 785 **Oil Hours** 0 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** F: x: Visc @ 40°C cSt 94.0 CONTAMINATION % Water NEG Silicon ppm 3 Sodium 0 🔲 ppm Potassium ppm 2 WEAR METALS PO 25 13 Iron ppm Copper 25 ppm Lead 0 ppm Tin 0 🔲 ppm Aluminum ppm 1 🔲 Chromium ppm 0 Molybdenum 107 ppm 0 🔲 Nickel ppm Titanium ppm <1 Silver 0 ppm Manganese 0 ppm Vanadium 0 ppm **ADDITIVES** Calcium 2420 ppm Magnesium ppm 64 Zinc ppm 1065 Phosphorus ppm 937 Barium 0 🔲 ppm Boron ppm 3



202 Banks St., One Little Harbor Landing OXFORD, MD US 21654 Contact: TRACY PELLERIN tpellerin@hinckleyyachts.com T: (410)770-4899

#### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot: VP592286 Unique No: 10751872 Signed: Jonathan Hester **Report Date:** 22 Nov 2023

Contact/Location: TRACY PELLERIN - VP592286

# **OIL ANALYSIS REPORT**



#### GRAPHS



Report Id: VP592286 [WUSCAR] 06012728 (Generated: 11/22/2023 15:36:03) Rev: 1

Contact/Location: TRACY PELLERIN - VP592286