



VPA050857 - OUTDRIVE - PORT GEARBOX

Sample No: VPA050857

Oil Type: GEAR OIL SAE 80W90

SAMPLE INFORM <i>e</i>	\TINN			
	ATION			
Sample Number		VPA050857	 	
Sample Date		14 Apr 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		SEVERE	 	
OIL CONDITION				
Visc @ 40°C	cSt	175	 	
CONTAMINATION				
Water	%	NEG	 	
Silicon	ppm	4	 	
Sodium	ppm	2 1	 	
Potassium	ppm	O	 	
WEAR METALS				
PQ		23	 	
Iron	ppm	▲ 764	 	
Copper	ppm	■ 4	 	
Lead	ppm	■0	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	■5	 	
Chromium	ppm	7	 	
Molybdenum	ppm	= <1	 	
Nickel	ppm	■4	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	
ADDITIVES				
Calcium	ppm	□ 56	 	
Magnesium		4	 	
Zinc	ppm	■ 4	 	
Phosphorus	ppm	1499	 	
•	ppm	_		
Barium	ppm	0		
Boron	ppm	155	 	

Steve's Marine Service West

255 S. Ketcham Ave. AMITYVILLE, NY US 11701 Contact: Steven Stavracos steve@stevesmarine.com T: (631)264-1600 F: (631).26-4.1601

Diagnosis

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:VP610610Unique No:10977729Signed:Jonathan HesterReport Date:16 Apr 2024

OIL ANALYSIS REPORT



