

# **OIL ANALYSIS REPORT**

Sample Rating Trend

ISO

Machine Id

# **PRESS 3 AFTER FILTER**

**Hydraulic System** 

PETRO CANADA HYDREX AW 68 (--- GAL)

### **DIAGNOSIS**

#### Recommendation

We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

#### Wear

All component wear rates are normal.

### Contamination

Particles >14µm are abnormally high. Particles >21µm are abnormally high. Particles >4µm are abnormally high. Particles >6µm are abnormally high.

#### **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Mar2021		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
			mmedase			
Sample Number		Client Info		WC0495635		
Sample Date	bro	Client Info		08 Mar 2021		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A ABNORMAL		
Sample Status				-		
CONTAMINATION	V	method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	<1		
Chromium	ppm	ASTM D5185(m)	>20	0		
Nickel	ppm	ASTM D5185(m)	>20	0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)	>20	<1		
Lead	ppm	ASTM D5185(m)	>20	0		
Copper	ppm	ASTM D5185(m)	>20	<1		
Tin	ppm	ASTM D5185(m)	>20	<1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1		
Barium	ppm	ASTM D5185(m)	0	0		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)	0	0		
Magnesium	ppm	ASTM D5185(m)	0	<1		
Calcium	ppm	ASTM D5185(m)	50	49		
Phosphorus	ppm	ASTM D5185(m)	330	297		
Zinc	ppm	ASTM D5185(m)	430	412		
Sulfur	ppm	ASTM D5185(m)	760	701		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	2		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	<1		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<b>19069</b>		
Particles >6µm		ASTM D7647	>1300	<u></u> 5818		
Particles >14µm		ASTM D7647	>160	<u>▲</u> 571		
Particles >21µm		ASTM D7647	>40	<u> </u>		
Particles >38µm		ASTM D7647	>10	6		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>^</u> 21/20/16		

Contact/Location: Chris Mayr - SPE95BRA



## **OIL ANALYSIS REPORT**





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

Lab Number : 02408688

Test Package : IND 2

: WC0495635 Unique Number : 5188165

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Received **Tested** 

: 11 Mar 2021 : 12 Mar 2021 Diagnosed : 12 Mar 2021 - Wes Davis

SPECTRA ALUMINUM PRODUCTS INC. 95 REAGENS INDUSTRIAL PKWY BRADFORD, ON

**CA L3Z 2A4** Contact: Chris Mayr cmayr@spectraaluminum.com

> T: (905)778-8093 F: (905)778-8054

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.