


OIL ANALYSIS REPORT

T20 JUMBO 21

Component

Diesel Engine

DIESEL ENGINE OIL SAE 40 (--- GAL)



DIAGNOSIS

Recommendation

We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. The oil change at the time of sampling has been noted. We recommend you service the filters on this component. We recommend an early resample to monitor this condition. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DIESEL ENGINE OIL SAE 40. Please confirm. Please specify the component make and model with your next sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate concentration of dirt present in the oil.


Fluid Condition

The oil is no longer serviceable due to the presence of contaminants.

				Aug2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0835145		
Sample Date		Client Info		31 Aug 2023		
Machine Age	hrs	Client Info		2402		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				ABNORMAL		
CONTAMINATION	١	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0		
Glycol		WC Method		NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>100	20		
Chromium	ppm	ASTM D5185(m)	>20	1		
Nickel	ppm	ASTM D5185(m)	>4	<1		
Titanium	ppm	ASTM D5185(m)		<1		
Silver	ppm	ASTM D5185(m)	>3	0		
Aluminum	ppm	ASTM D5185(m)	>20	6		
Lead	ppm	ASTM D5185(m)	>40	1		
Copper	ppm	ASTM D5185(m)	>330	8		
Tin	ppm	ASTM D5185(m)	>15	<1		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	250	65		
Barium	ppm	ASTM D5185(m)	10	1		
Molybdenum	ppm	ASTM D5185(m)	100	68		
Manganese	ppm	ASTM D5185(m)		2		
Magnesium	ppm	ASTM D5185(m)	450	497		
Calcium	ppm	ASTM D5185(m)	3000	1797		
Phosphorus	ppm	ASTM D5185(m)	1150	1116		
Zinc	ppm	ASTM D5185(m)	1350	1228		
Sulfur	ppm	ASTM D5185(m)	4250	3474		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>25	△ 35		
Sodium	ppm	ASTM D5185(m)	>216	4		
Potassium	ppm	ASTM D5185(m)	>20	3		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*	>3	0		
Nitration	Abs/cm	ASTM D7624*	>20	8.0		
Sulfation	Abs/.1mm	ASTM D7415*	>30	21.7		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	ASTM D7414*	>25	17.1		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9

: WC0835145 : 02580209 : 5633269

Received Diagnosed Diagnostician

: 05 Sep 2023 : 05 Sep 2023 : Kevin Marson

Agnico Eagle Canada 1350 Government Rd. W, MACASSA COMPLEX

Kirkland Lake, ON **CA P2N 3J1**

Contact: Mike Campbell mike.campbell@agnicoeagle.com

T: (705)567-5208 F: (705)567-5221

Validity of results and interpretation are based on the sample and information as supplied.

Contact/Location: Mike Campbell - KIR370KIR