

OIL ANALYSIS REPORT

Copper

Antimony

Vanadium

Beryllium

Cadmium

Tin

Sample Rating Trend



NORMAL



SAB2 **SAB2 G16**

Component **Thrust Bearing**

ESSO TERESSO ISO 46 (5000 LTR)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor. Please contact your representative for information regarding the proper sampling kits for your service. NOTE: We recommend using IND 3 test kits, this testkit includes Analytical Ferrography which provides a detailed morphological analysis of wear particles present in the fluid.

Component wear rates appear to be normal (unconfirmed).

Contamination

The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

3/113 New/2014 Jan/2015 Aux/2013 Jan/2013 Jan/2013 Jan/2013 Oct/202							
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2	
Sample Number		Client Info		WC0858076	WC0830376	WC0780498	
Sample Date		Client Info		25 Oct 2023	31 Jul 2023	05 Jun 2023	
Machine Age	hrs	Client Info		0	0	0	
Oil Age	hrs	Client Info		0	0	0	
Oil Changed		Client Info		N/A	N/A	N/A	
Sample Status				NORMAL	NORMAL	NORMAL	
WEAR METALS		method	limit/base	current	history1	history2	
Iron	ppm	ASTM D5185(m)	>85	3	3	3	
Chromium	ppm	ASTM D5185(m)	>20	0	0	0	
Nickel	ppm	ASTM D5185(m)	>20	0	0	<1	
Titanium	ppm	ASTM D5185(m)		0	0	0	
Silver	ppm	ASTM D5185(m)		<1	0	0	
Aluminum	ppm	ASTM D5185(m)	>40	0	0	<1	
Lead	ppm	ASTM D5185(m)	>60	<1	<1	<1	

ASTM D5185(m) >7

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m)

ASTM D5185(m)

ppm

ppm

ppm

ppm

ppm

ppm

ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1	0	<1
Barium	ppm	ASTM D5185(m)		<1	0	0
Molybdenum	ppm	ASTM D5185(m)	0	0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)	0	0	0	<1
Calcium	ppm	ASTM D5185(m)	0	<1	<1	0
Phosphorus	ppm	ASTM D5185(m)	2.4	0	<1	0
Zinc	ppm	ASTM D5185(m)	0	<1	2	<1
Sulfur	ppm	ASTM D5185(m)		647	711	642
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2

0

0

0

0

0

0 0

0


0

0

0

0

Silicon	ppm	ASTM D5185(m)	>20	<1	<1	<1
Sodium	ppm	ASTM D5185(m)		0	0	0
Potassium	ppm	ASTM D5185(m)	>20	0	<1	0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	684	603	468
Particles >6µm		ASTM D7647	>1300	68	75	60
Particles >14μm		ASTM D7647	>160	6	6	6
Particles >21µm		ASTM D7647	>40	3	2	2
Particles >38μm		ASTM D7647	>10	1	0	0
Particles >71μm		ASTM D7647	>3	1	0	0
Oil Cleanliness		ISO 4406 (c)	>20/17/14	17/13/10	16/13/10	16/13/10
FLUID DEGRADATION		method	limit/base	current	history1	history2



Acid Number (AN)

mg KOH/g ASTM D974* 0.02


0.11

0.04

0.07 Submitted By: ?



OIL ANALYSIS REPORT







Report Id: ONTQUE [WCAMIS] 02592141 (Generated: 10/30/2023 16:20:51) Rev: 1

Laboratory Sample No. Lab Number **Unique Number**

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : WC0858076 : 02592141

Received Diagnosed : 5669220 Diagnostician : Kevin Marson

: 26 Oct 2023 : 30 Oct 2023

Ontario Power Generation NIAGARA PLANT GROUP,, 14000 NIAGARA PKWY NIAGARA ON THE LAKE, ON

CA LOS 1J0

Test Package : IND 2 (Additional Tests: BottomAnalysis, FilterPatch, PrtFilter, TAN Macontact: Alex Courtemanche To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

alex.courtemanche@opg.com T: (905)357-0322 F: (905)357-6558