


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



SPARTAN X LIFT SL16

Component

Transmission

SAE 15W40 (--- GAL)

Recommendation

The fluid change at the time of sampling has been noted. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the fluid.

Fluid Condition

The condition of the fluid is acceptable for the time in service.

				Dec2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0861417		
Sample Date		Client Info		10 Dec 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				NORMAL		
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>200	4		
Chromium	ppm	ASTM D5185(m)	>10	0		
Nickel	ppm	ASTM D5185(m)		<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		<1		
Aluminum	ppm	ASTM D5185(m)	>50	2		
Lead	ppm	ASTM D5185(m)	>50	60		
Copper	ppm	ASTM D5185(m)	>200	15		
Tin	ppm	ASTM D5185(m)	>10	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		22		
Barium	ppm	ASTM D5185(m)		<1		
Molybdenum	ppm	ASTM D5185(m)		49		
Manganese	ppm	ASTM D5185(m)		0		
Magnesium	ppm	ASTM D5185(m)		759		
Calcium	ppm	ASTM D5185(m)		1368		
Phosphorus	ppm	ASTM D5185(m)		928		
Zinc	ppm	ASTM D5185(m)		1071		
Sulfur	ppm	ASTM D5185(m)		2905		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	5	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	5		
Sodium	ppm	ASTM D5185(m)	>57	2		
				_		

ASTM D5185(m) >20


ppm

0

Potassium



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number **Unique Number**

: WC0861417

ਲੂੱ 100

: 02603532 : 5696617 Test Package : MOB 1

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 : 15 Dec 2023 Recieved Diagnosed

: 18 Dec 2023 : Kevin Marson Diagnostician

Agnico Eagle Canada 1350 Government Rd. W, MACASSA COMPLEX

phosphorus -----

Kirkland Lake, ON CA P2N 3J1

Contact: Mitch Lamontagne

 $AEM_KL_macassao il samplere sults@agnico eagle.com$

T: (705)567-5208

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Validity of results and interpretation are based on the sample and information as supplied.

F: (705)567-5221