

OIL ANALYSIS REPORT

Sample Rating Trend

WATER

1-32500 FM1 ID FAN #1

Component

Outboard Bearing

MOBIL SHC 624 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. We advise that you check all areas where dirt can enter the system. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you follow the water drain-off procedure for this component. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. Confirm the source of the lubricant being utilized for topup/fill. We recommend an early resample to monitor this condition. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

Free water present. Elemental level of silicon (Si) above normal indicating ingress of seal material.


Fluid Condition

Additive levels indicate the addition of a different brand, or type of oil. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

	Sep2022 Dec2022 Junt2023					
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0822010	WC0764655	WC0706909
Sample Date		Client Info		10 Jun 2023	10 Dec 2022	07 Sep 2022
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>20	9	13	10
Chromium	ppm	ASTM D5185(m)	>20	0	0	0
Nickel	ppm	ASTM D5185(m)	>20	<1	<1	<1
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		<1	0	0
Aluminum	ppm	ASTM D5185(m)	>20	<1	<1	0
Lead	ppm	ASTM D5185(m)	>20	3	5	2
Copper	ppm	ASTM D5185(m)	>20	4	6	2
Tin	ppm	ASTM D5185(m)	>20	8	11	13
Antimony	ppm	ASTM D5185(m)		<1	<1	1
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		<1	0	<1
Barium	ppm	ASTM D5185(m)		0	0	0
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	<1
Magnesium	ppm	ASTM D5185(m)		0	<1	0
Calcium	ppm	ASTM D5185(m)		<1	<1	<1
Phosphorus	ppm	ASTM D5185(m)		65	63	507
Zinc	ppm	ASTM D5185(m)		4	5	7
Sulfur	ppm	ASTM D5185(m)		1564	1493	17
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	<u> </u>	11	9
Sodium	ppm	ASTM D5185(m)		0	0	0
Potassium	ppm	ASTM D5185(m)	>20	0	<1	0



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	VLITE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	NONE	VLITE	NONE
Debris	scalar	Visual*	NONE	NONE	VLITE	NONE
Sand/Dirt	scalar	Visual*	NONE	VLITE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>2	.2%	.2%	NEG
Free Water	scalar	Visual*		<u>^</u> 5%	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	historv2

600 T		
500 - calcium phospho	orus	
400 -		
E 300-		
200		
100		
0	***************************************	
, 22/1	0/22	0/23
Sep7/	Dec1	Jun10

I LOID I HOI LIH		momod	III III Daoo	Odiront	Thotory I	i notor y
Visc @ 40°C	cSt	ASTM D7279(m)	32.4	32.0	31.8	31.9


method




Color

Bottom


SAMPLE IMAGES






GRAPHS

Ferrous Alloys







CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No. Lab Number Unique Number : 5697247

: WC0822010 : 02604162

: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 Recieved : 19 Dec 2023 Diagnosed

: 20 Dec 2023 Diagnostician : Kevin Marson

Test Package : IND 1

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

Ontario Power Generation ATIKOKAN T.G.S., BOX 1900

ATIKOKAN, ON CA POT 1C0 Contact: Dale Anthony

dale.anthony@opg.com

F: (807)597-1198

Submitted By: ?