



- -

# **OIL ANALYSIS REPORT**

Sample Rating Trend







WEAR

### ICI EMKARATE RL 46H (--- GAL)

		$\sim$			$\sim$	
DI	Δ	сı	NΙ(		51	S
		$\sim$		$\sim$		$\mathbf{U}$

#### Recommendation

Resample at the next service interval to monitor.

Component Chiller Fluid

#### Wear

Copper ppm levels are noted. The elevated copper reading suggests the effects of oil migration through the evaporator (oil loss from the compressor) possibly occurring during intervals of operation at low cooling load conditions.

#### Contamination

The water content is negligible. There is no indication of any contamination in the oil.

#### Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GTT0001497	GTT17802	GTT17803
Sample Date		Client Info		17 Jan 2024	17 Nov 2022	18 Nov 2016
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>100	6	<1	12
Chromium	ppm	ASTM D5185(m)	>2	0	<1	<1
Nickel	ppm	ASTM D5185(m)		<1		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)	>2	0		
Aluminum	ppm	ASTM D5185(m)	>50	<1	<1	1
Lead	ppm	ASTM D5185(m)	>2	1	<1	2
Copper	ppm	ASTM D5185(m)	>100	<b>1</b> 2	3	1
Tin	ppm	ASTM D5185(m)	>4	<1	<1	<1
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	1		
Barium	ppm	ASTM D5185(m)	0	0		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)	0	0		
Magnesium	ppm	ASTM D5185(m)	0	<1		
Calcium	ppm	ASTM D5185(m)	0	<1		
Phosphorus	ppm	ASTM D5185(m)	1900	2195		
Zinc	ppm	ASTM D5185(m)	0	20	3	28
Sulfur	ppm	ASTM D5185(m)	25	83		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS	i -	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	8		
Sodium	ppm	ASTM D5185(m)		<1		
Potassium	ppm	ASTM D5185(m)	>20	<1		
ppm Water	ppm	ASTM D6304*	>400	101	166	65
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.03	0.11	0.030	0.150



## **OIL ANALYSIS REPORT**

VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	46.8	34.8		
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image
GRAPHS						



 Lab Number
 : 02610079
 Diagnosed
 : 24 Jan 2024

 Unique Number
 : 5711165
 Diagnostician
 : Bill Quesnel

 Test Package
 : IND 2 (Additional Tests: KV40)
 : Bill Quesnel

 To discuss this sample report, contact Customer Service at 1-905-847-9300 Ext 26.
 Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

 Damages: Seller shall in no event be liable for special, incidental, or consequential damages, of a commercial nature, resulting from any cause.

: 19 Jan 2024

Recieved

Complete Chiller Solutions 8-4444 Eastgate Parkway Mississauga, ON CA L4W 4T6 Contact: Service Manager ap@complete-cs.ca T: (905)629-8585 F:

Sample No.

: GTT0001497

Contact/Location: Service Manager - GTT0000508