

### **OIL ANALYSIS REPORT**

# [22189738] #182-109 Rotary Wet Screw Air Comp

Screw Compressor

Fluid SULLAIR SULLUBE 32 (114 LTR)

#### DIAGNOSIS

#### A Recommendation

We advise that you check for the source of water entry. Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. The oil is near the end of it's useful service life, recommend schedule an oil change. We recommend an early resample to monitor this condition.

#### Wear

All component wear rates are normal.

#### Contamination

There is a moderate concentration of water present in the oil.

#### Fluid Condition


The AN level is above the recommended limit. Viscosity of sample indicates oil is within ISO 68 range, advise investigate. The oil is no longer serviceable.




SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0870422	WC0749138	WC0840184
Sample Date		Client Info		12 Apr 2024	11 Jan 2024	10 Oct 2023
Machine Age	mths	Client Info		0	0	0
Oil Age	mths	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0	0	0
Iron	ppm	ASTM D5185(m)	>60	<1	<1	0
Chromium	ppm	ASTM D5185(m)	>4	0	0	0
Nickel	ppm	ASTM D5185(m)		<1	<1	0
Titanium	ppm	ASTM D5185(m)		0	0	0
Silver	ppm	ASTM D5185(m)		0	0	<1
Aluminum	ppm	ASTM D5185(m)		0	<1	0
Lead	ppm	ASTM D5185(m)	>10	0	0	<1
Copper	ppm	ASTM D5185(m)	>30	<1	<1	<1
Tin	ppm	ASTM D5185(m)	>15	0	0	0
Antimony	ppm	ASTM D5185(m)		0	0	0
Vanadium	ppm	ASTM D5185(m)		0	0	0
Beryllium	ppm	ASTM D5185(m)		0	0	0
Cadmium	ppm	ASTM D5185(m)		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		3	4	3
Barium	ppm	ASTM D5185(m)	745	309	200	154
Molybdenum	ppm	ASTM D5185(m)		0	0	0
Manganese	ppm	ASTM D5185(m)		0	0	0
Magnesium	ppm	ASTM D5185(m)		<1	<1	0
Calcium	ppm	ASTM D5185(m)	1	4	2	2
Phosphorus	ppm	ASTM D5185(m)	3	1	<1	1
Zinc	ppm	ASTM D5185(m)		9	4	3
Sulfur	ppm	ASTM D5185(m)		357	348	278
Lithium	ppm	ASTM D5185(m)		<1	<1	<1
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>50	6	6	4
Sodium	ppm	ASTM D5185(m)		94	87	80
Potassium	ppm	ASTM D5185(m)	>20	12	12	9
Water	%	ASTM D6304*	>0.1	<b>6</b> 0.277	<b>0</b> .195	<b>0</b> .358
ppm Water	ppm	ASTM D6304*	>1000	<b>A</b> 2771	<b>1</b> 954	▲ 3580.1
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		<b>6.09</b>	3.16	2.77




## **OIL ANALYSIS REPORT**










VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Yellow Metal	scalar	Visual*	NONE	NONE	NONE	NONE
Precipitate	scalar	Visual*	NONE	NONE	NONE	NONE
Silt	scalar	Visual*	NONE	VLITE	NONE	NONE
Debris	scalar	Visual*	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	Visual*	NONE	NONE	NONE	NONE
Appearance	scalar	Visual*	NORML	NORML	NORML	NORML
Odor	scalar	Visual*	NORML	NORML	NORML	NORML
Emulsified Water	scalar	Visual*	>0.1	NEG	NEG	NEG
Free Water	scalar	Visual*		NEG	NEG	NEG
FLUID PROPERT	IES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	32.0	▲ 68.2	▲ 56.0	▲ 50.0
SAMPLE IMAGES	6	method	limit/base	current	history1	history2
Color						
Bottom						



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 CALA Sample No. : WC0870422 Received : 19 Apr 2024 Lab Number : 02630240 Tested : 22 Apr 2024 ISO 17025:2017 Accredited Laboratory Unique Number : 5763372 Diagnosed : 22 Apr 2024 - Kevin Marson Test Package : IND 2 ( Additional Tests: KF, TAN Man ) To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

**ARAUCO - St. Stephen** 151 Church Street St. Stephen, NB CA E3L 3A6 Contact: Jim Sears Jim.Sears@arauco.com T: (506)465-2858 F: (506)465-2831

Report Id: FLASTS [WCAMIS] 02630240 (Generated: 04/22/2024 09:23:26) Rev: 1

Contact/Location: Jim Sears - FLASTS Page 2 of 2