

OIL ANALYSIS REPORT

Area **unassigned T001422 (S/N 24-M-05-2640)**

Hydraulic System

PETRO CANADA HYDREX XV ALL SEASON HYDRAULIC OIL (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.

Wear


All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition


The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.





SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0937642		
Sample Date		Client Info		17 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG		
WEAR METALS		method	limit/base	current	history1	history2
PQ		ASTM D8184*		0		
Iron	ppm	ASTM D5185(m)	>20	<1		
Chromium	ppm	ASTM D5185(m)	>20	0		
Nickel	ppm	ASTM D5185(m)	>20	0		
Titanium	ppm	ASTM D5185(m)		0		
Silver	ppm	ASTM D5185(m)		1		
Aluminum	ppm	ASTM D5185(m)	>20	0		
Lead	ppm	ASTM D5185(m)	>20	0		
Copper	ppm	ASTM D5185(m)	>20	<1		
Tin	ppm	ASTM D5185(m)	>20	0		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)	0	<1		
Barium	ppm	ASTM D5185(m)	0	<1		
Molybdenum	ppm	ASTM D5185(m)	0	0		
Manganese	ppm	ASTM D5185(m)	1	0		
Magnesium	ppm	ASTM D5185(m)	0	1		
Calcium	ppm	ASTM D5185(m)	100	95		
Phosphorus	ppm	ASTM D5185(m)	670	623		
Zinc	ppm	ASTM D5185(m)	850	809		
Sulfur	ppm	ASTM D5185(m)	1600	1467		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185(m)	>15	2		
Sodium	ppm	ASTM D5185(m)		0		
Potassium	ppm	ASTM D5185(m)	>20	<1		



OIL ANALYSIS REPORT







FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	_ 10836		
Particles >6µm		ASTM D7647	>1300	<mark> </mark> 1739		
Particles >14µm		ASTM D7647	>160	37		
Particles >21µm		ASTM D7647	>40	9		
Particles >38µm		ASTM D7647	>10	3		
Particles >71µm		ASTM D7647	>3	2		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	A 21/18/12		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*	0.60	0.70		
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	Visual*	NONE	NONE		
Yellow Metal	scalar	Visual*	NONE	NONE		
Precipitate	scalar	Visual*	NONE	NONE		
Silt	scalar	Visual*	NONE	NONE		
Debris	scalar	Visual*	NONE	NONE		
Sand/Dirt	scalar	Visual*	NONE	NONE		
Appearance	scalar	Visual*	NORML	NORML		
Odor	scalar	Visual*	NORML	NORML		
Emulsified Water	scalar	Visual*	>0.05	NEG		
Free Water	scalar	Visual*		NEG		
FLUID PROPERT	TIES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D7279(m)	47.9	47.1		
SAMPLE IMAGES	S	method	limit/base	current	history1	history2
Color					no image	no image

Bottom



Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9 CALA : WC0937642 Received : 18 Jun 2024 Sample No. Lab Number : 02642597 Tested : 20 Jun 2024 ISO 17025:2017 Accredited Laboratory Unique Number : 5800136 Diagnosed : 20 Jun 2024 - Wes Davis Test Package : MOB 2 (Additional Tests: PQ, TAN Auto) To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

873 Devonshire Ave. Woodstock, ON CA N4S 8Z4 Contact: Tami Arnold tamia@rwfbron.com T: F: (519)421-0028

RWF Industries

Report Id: RWFWOO [WCAMIS] 02642597 (Generated: 06/20/2024 09:28:06) Rev: 1

Contact/Location: Tami Arnold - RWFWOO Page 2 of 2

no image

no image