


OIL ANALYSIS REPORT

Sample Rating Trend



AUDI AUDI RS7

Component

Gasoline Engine

{not provided} (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. We recommend that you drain the oil from the component if this has not already been done. We recommend you service the filters on this component. We recommend an early resample to monitor this condition. Please specify the brand, type, and viscosity of the oil on your next sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate concentration of water present in the oil. There is a moderate concentration of dirt present in the oil. Test for glycol is negative.

Fluid Condition

The oil is no longer serviceable due to the presence of contaminants.

				Jun 2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0956587		
Sample Date		Client Info		11 Jun 2024		
Machine Age	kms	Client Info		0		
Oil Age	kms	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION	V	method	limit/base	current	history1	history2
Fuel		WC Method	>4.0	<1.0		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)	>150	15		
Chromium	ppm	ASTM D5185(m)	>20	<1		
Nickel	ppm	ASTM D5185(m)	>5	0		
Titanium	ppm	ASTM D5185(m)		<1		
Silver	ppm	ASTM D5185(m)	>2	0		
Aluminum	ppm	ASTM D5185(m)	>40	8		
Lead	ppm	ASTM D5185(m)	>50	29		
Copper	ppm	ASTM D5185(m)	>155	3		
Tin	ppm	ASTM D5185(m)	>10	2		
Antimony	ppm	ASTM D5185(m)		0		
Vanadium	ppm	ASTM D5185(m)		0		
Beryllium	ppm	ASTM D5185(m)		0		
Cadmium	ppm	ASTM D5185(m)		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185(m)		219		
Barium	ppm	ASTM D5185(m)		0		
Molybdenum	ppm	ASTM D5185(m)		146		
Manganese	ppm	ASTM D5185(m)		<1		
Magnesium	ppm	ASTM D5185(m)		18		
Calcium	ppm	ASTM D5185(m)		2151		
Phosphorus	ppm	ASTM D5185(m)		800		
Zinc	ppm	ASTM D5185(m)		925		
Sulfur	ppm	ASTM D5185(m)		1895		
Lithium	ppm	ASTM D5185(m)		<1		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon		ASTM D5185(m)	>30	<u> 48</u>		
	ppm	ASTM D5185(m) ASTM D5185(m)		48 5		
Sodium	ppm	(/	>400	2		
Potassium	ppm o/	ASTM D6304*	>20			
Water	%	ASTM D6304* ASTM D6304*	>0.2	△ 0.501 △ 5014		
ppm Water Glycol	ppm %	ASTM D0304 ASTM D7922*	>2000	0.0		
	70			0.0		
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	ASTM D7844*		0		
Nitration	Abs/cm	ASTM D7624*	>20	9.7		
Sulfation	Abs/.1mm	ASTM D7415*	>30	14.0		



OIL ANALYSIS REPORT





CALA ISO 17025:2017 Accredited Laboratory

Laboratory Sample No.

: WC0956587 Lab Number : 02642885

Unique Number : 5800424

Received : 19 Jun 2024 **Tested** : 21 Jun 2024 Diagnosed : 21 Jun 2024 - Kevin Marson

Test Package : MOB 1 (Additional Tests: Glycol, KF, KV40, VI, Visual)

To discuss this sample report, contact Customer Service at 1-800-268-2131. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab. Validity of results and interpretation are based on the sample and information as supplied.

242 Mud St West Grassy, ON CA LOR 1M0 Contact: Luke Kacznarczyk lukeabc123@hotmail.ca T: (905)531-3486